

**कार्यपालक अभियन्ता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, भभुआ**

पत्रांक.....523../भभुआ,

दिनांक.....17.03.23.....

प्रेषक,

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, भभुआ

सेवामें,

अपर-मुख्य कार्यपालक पदाधिकारी,
सह-सचिव, बी0आर0आर0डी0ए0,
बिहार, पटना।

विषय:- MR/3054 मरम्मत योजना अन्तर्गत मरम्मत कार्य की अधियाचना के संबंध में।


महाशय,

उपर्युक्त विषय के संबंध में इस प्रमंडल में MR/3054 मरम्मत योजना अन्तर्गत मरम्मत कार्य हेतु अधियाचना विहित प्रपत्र में अंकित कर सूचनार्थ एवम् आवश्यक कार्यवाही हेतु समर्पित की जाती है।

सूचनार्थ समर्पित।

अनु0:- यथोक्त।


विश्वासभाजन



कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, भभुआ

ज्ञापांक.....523...../भभुआ, दिनांक.....17.03.23.....

प्रतिलिपि :- नोडल पदाधिकारी, MR/3054 ब्राडा, पटना को सूचनार्थ समर्पित।



कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल भभुआ



Name of Works Division : Bhabhua

[illegible]

Executive Engineer,
RWD Work Division Bhabhua

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to date

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	7999.60740	Certified that out of 7999.60740 lakh of grants-in-aid sanctioned during the years 2022-23 In favor of EE,RWD works division Bhabhua a sum of Rs.7829.42257 lakh has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs.170.18483 lakh remaining unutilized at the end of the period under report.
	Total:		7999.60740	

2. Certified that I have satisfied my self that the cosnditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.

Sund Kund
17/12/23
Divisional Accounts Officer
R.W.D, works Division
Bhabhua.

17/12/23
Executive Engineer
R.W.D, works Division
Bhabhua
17/12/23

Road Name -1054-Rudrawar Bhabhua Road T04 to Saitha (VR44)

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
17/3/23	8:7:6	63	0.1	190	0	1900	2290 G		25.26647	83.635353	Normal
17/3/23	8:7:53	63	0.1	300	30.3	3000	3540 G		25.26727	83.634377	Normal
17/3/23	8:8:11	63	0.1	280	30.3	2800	3313 G		25.26807	83.63338	Normal
17/3/23	8:8:54	63	0.1	270	30.3	2700	3199 G		25.25968	83.634537	Normal
17/3/23	8:9:14	63	0.1	310	30.3	3100	3654 G		25.18678	83.63345	Curve
17/3/23	8:9:13	63	0.1	260	30.3	2600	3086 G		25.17876	83.63479	Normal
17/3/23	8:10:12	63	0.1	290	30.3	2900	3426 G		25.17438	83.635404	Normal
17/3/23	8:10:51	63	0.1	250	40.4	2500	2972 G		25.16847	83.63604	Normal
17/3/23	8:11:17	63	0.1	300	30.3	3000	3540 G		25.15888	83.636078	Normal
17/3/23	8:11:50	63	0.1	280	30.3	2800	3313 G		25.15061	83.635948	Normal
17/3/23	8:12:14	63	0.1	300	30.3	3000	3540 G		25.14565	83.36747	Normal
17/3/23	8:12:56	63	0.1	260	40.4	2600	3086 G		25.14096	83.637517	Normal
17/3/23	8:13:20	63	0.1	300	30.3	3000	3540 G		25.136887	83.636915	Normal
17/3/23	8:13:58	63	0.1	310	30.3	3100	3654 G		25.13084	83.636667	Normal
17/3/23	8:14:20	63	0.1	290	30.3	2900	3426 G		25.12153	83.636655	Curve
17/3/23	8:14:55	63	0.1	300	30.3	3000	3540 G		25.11354	83.636918	Normal
17/3/23	8:15:15	63	0.1	250	40.4	2500	2972 G		25.108076	83.637835	Normal
17/3/23	8:15:53	63	0.1	300	30.3	3000	3540 G		25.10311	83.63803	Normal
17/3/23	8:16:11	63	0.1	280	30.3	2800	3313 G		25.11315	83.637871	Normal
17/3/23	8:16:51	63	0.1	310	30.3	3100	3654 G		25.115423	83.638674	Normal
17/3/23	8:17:17	63	0.1	240	40.4	2400	2858 G		25.11383	83.638277	Curve
17/3/23	8:17:52	63	0.1	280	30.3	2800	3313 G		25.115362	83.638631	Normal
17/3/23	8:18:21	63	0.1	310	30.3	3100	3654 G		25.115379	83.638667	Normal
17/3/23	8:19:38	63	0.1	290	30.3	2900	3426 G		25.115712	83.638314	Normal
17/3/23	8:20:38	63	0.1	200	0	2000	2404 G		25.115834	83.6386752	Normal

$Y = 0 * X^2 + 1.136 * X + 132.5$
 $X = 2000$
 $Y = 2404$
 (R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001

Total IRI
 Average 3290.12

17.03.23
 J.E

17.3.23
 A.E

17.3.23

Name of Customer : Anshuman Kumar Singh
 Name of Work : U54 Rudrewar Bhabhua Road
 Road :
 Lab Job number : 63
 Date : 17-03-2023
 Section No. : 63


Test Date : 17-03-2023
 Road Name : U54-Rudrewar Bhabhua Road
 Machine No : 412
 Road Type : (R) RURAL ROAD
 Start S No :
 Start E No :
 Side :
 Weather :
 UIV Range : 1290 To 5000 mm/km
 Dist Range : 0 To 26 01 1000 m
 End Location :
 Equation : $Y = 0.0 \cdot X^2 + 2.1136 \cdot X + 1325$

Print Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\BPRDA31\OneDrive\Desktop\sk3\new Mr Bump 22-23\anshuman\U54-Rudrewar Bhabhua Road
 Name of Customer : Name of Work/ Road : Lab Job number :



Druid
 17.3.23
 SE

17.3.23
 AF

17.3.23