

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक-.....५१५...../बक्सर

दिनांक-...१७/०३/२३.....

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मति (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


१७/०३/२३
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर


१७/०३/२३

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 32, dt.-03.03.2023	6985.97121	Certified that out of Rs. 6985.97121 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 6966.02771 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 19.90435 lacs remaining unutilized at the end of the period under
Total -				

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works
- Construction of CD works

16.03.23
Executive Engineer

R.W.D. (w) Div. Buxar

AK
16.03.23

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (In Lakh)	up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (In KM)	Amount (In Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
1	RM/BU/BU X/22/0001	CHAMILLA TO INTAUNHA VIA MANGOLPUR ROAD	10401912009	Letter No 852 & 18/02/2022	3.600	140.59	62.68138	27.85769	10/MBD/2022-23 & 30.11.2022	29.08.2023	2693	25 mm	5.00%	56.8819	56.69883	4.44906	
2	RM/BU/BU X/22/0001	BUXAR DHANSOI BASWAN KALA ROAD TO BRADIH AUR PUL PAR GIRDARPUR TO GOPPUR	10401913006	Letter No 852 & 18/02/2022	3.500	156.47	74.08954	30.04877	10/MBD/2022-23 & 30.11.2022	29.08.2023	2980	25mm	5.01%	62.1319	61.18499	4.07634	
3	RM/BU/BU X/22/0001	Dhansoi Chousa Road to Chilibili Road Via Kaithna H.S.	10401901009	Letter No 852 & 18/02/2022	3.500	152.47	81.7235	30.6694	10/MBD/2022-23 & 30.11.2022	29.08.2023	2955	25mm	5.01%	0	0	79.39692	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W), Div.- Buxar


17.03.23
17/03/23

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स...415..... बक्सर/ दिनांक...17/03/23...

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Chausa Dhansoi Road to Kaithna High School to Chilbila Siwan पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


 16/03-23

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा बक्सर

 17/03-23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : E:\maatarachandi 3\16031905.Xls. Section No. :2. Eqn :test
 Name of Customer :Maa Tarachandi Construction. Name of Work/Road :Chausa Thansoi Road To Kaithna high



[Signature]
 16.03.23

[Signature]
 16.03.23

[Signature]
 17.03.23

Name of Road:- Chausa Dhansoi Road Kaithna High School To Chilbila Siwan Contractor's Name:- Maa Tarachndi Construction

Date	Time	Section	No.	Length in km	Bumps in mm	Rate	Speed mm/km	OR	IRI, TEGORY	Latitude	ongitude	Event
16/3/23	18:36:5	2	0.1	220	10.1	2200	2631 G		25.40343	83.99258	Normal	$Y = 0 * X^2 + 1.136 * X + 132.5$
16/3/23	18:36:40	2	0.1	230	10.1	2300	2745 G		25.40248	83.99266	Normal	$X = 3261$
16/3/23	18:37:0	2	0.1	260	10.1	2600	3086 G		25.40156	83.99269	Normal	$Y = 3836$
16/3/23	18:37:16	2	0.1	210	10.1	2100	2518 G		25.40114	83.99197	Normal	
16/3/23	18:38:0	2	0.1	190	10.1	1900	2290 G		25.40105	83.99098	Speed Breaker	
16/3/23	18:39:1	2	0.1	190	10.1	1900	2290 G		25.40094	83.98993	Normal	(R) RURAL ROAD
16/3/23	18:39:37	2	0.1	230	10.1	2300	2745 G		25.40001	83.98992	Normal	Good Average Poor
16/3/23	18:40:12	2	0.1	250	10.1	2500	2972 G		25.39906	83.98992	Normal	<4000 4001-5000 >5001
16/3/23	18:40:12	2	0.1	310	10.1	3100	3654 G		25.39813	83.98992	Normal	IRI Value=2955
16/3/23	18:41:0	2	0.1	260	10.1	2600	3086 G		25.39715	83.98993	Normal	Machine ID=415
16/3/23	18:41:23	2	0.1	230	10.1	2300	2745 G		25.39626	83.98992	Normal	
16/3/23	18:41:23	2	0.1	260	10.1	2600	3086 G		25.39528	83.98992	Normal	
16/3/23	18:42:0	2	0.1	320	10.1	2600	2967 G		25.39434	83.98992	Normal	
16/3/23	18:42:33	2	0.1	340	10.1	2800	2810 G		25.39344	83.98993	Normal	
16/3/23	18:43:0	2	0.1	330	10.1	3300	3881 G		25.39249	83.98997	Normal	
16/3/23	18:43:44	2	0.1	260	10.1	1500	1968 G		25.39154	83.99007	Normal	
16/3/23	18:46:5	2	0.1	250	10.1	2500	2972 G		25.39161	83.98909	Normal	
16/3/23	18:46:5	2	0.1	380	10.1	1900	2272 G		25.39171	83.98808	Normal	
16/3/23	18:47:51	2	0.1	280	10.1	1900	2256 G		25.39167	83.98712	Normal	
16/3/23	18:48:0	2	0.1	350	10.1	3500	4108 G		25.39181	83.98613	Normal	
16/3/23	18:49:1	2	0.1	300	10.1	3000	3540 G		25.39195	83.98508	Normal	
16/3/23	18:50:0	2	0.1	290	10.1	2900	3426 G		25.39164	83.98448	Normal	
16/3/23	18:50:12	2	0.1	350	10.1	1700	2109 G		25.39074	83.98423	Normal	
16/3/23	18:51:0	2	0.1	230	10.1	2300	2745 G		25.39024	83.98365	Normal	
16/3/23	18:51:22	2	0.1	190	10.1	1900	2290 G		25.39055	83.98269	Normal	
16/3/23	18:52:0	2	0.1	300	10.1	3000	3540 G		25.39071	83.982	Normal	
16/3/23	18:54:19	2	0.1	240	10.1	2400	2858 G		25.39099	83.98084	Normal	
16/3/23	18:55:0	2	0.1	310	10.1	3100	3654 G		25.39097	83.97987	Normal	
16/3/23	18:55:29	2	0.1	400	10.1	4000	4676 G		25.39006	83.98	Normal	
16/3/23	18:56:5	2	0.1	310	10.1	3100	3654 G		25.38931	83.97958	Normal	
16/3/23	18:56:5	2	0.1	370	10.1	3700	4335 G		25.38837	83.97975	Normal	
16/3/23	18:56:40	2	0.1	340	10.1	3400	3994 G		25.38746	83.97995	Normal	
16/3/23	18:57:15	2	0.1	430	10.1	1800	2109 G		25.38655	83.9801	Normal	
16/3/23	18:59:1	2	0.1	150	10.1	1900	1659 G		25.38606	83.98013	Normal	
16/3/23	19:00:15	2	0.1	150	10.1	1900	1769 G		25.38603	83.98015	Normal	

16/3/23

16.03.23

17.03.23