

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिवान-2

पत्रांक 4103/30 सिवान, दिनांक 17-3-23

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सिवान-2

सेवा में,

सचिव-सह-प्राधिकृत पदाधिकारी
बिहार ग्रामीण पथ विकास एजेन्सी
भूमि विकास बैंक भवन
बुद्ध मार्ग, पटना।

विषय:- योजना शीर्ष नई अनुरक्षण निति 2018 MR/3054 अन्तर्गत पथों में मरम्मत हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के आलोक में कहना है कि योजना शीर्ष नई अनुरक्षण निति 2018 MR/3054 अन्तर्गत संलग्न विहित प्रपत्र में 1.38703 लाख (एक लाख अड़तीस हजार सात सौ तीन) रुपये मात्र आवंटन देने की कृपा की जाय।

अनु0-अधियाचना पत्र, Bump Integrator Equipment Report की छाया प्रति,
एकरारनामा की छाया प्रति,

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सिवान-2

17.3.23

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- RWD, WORKS DIVISION, SIWAN-2

S.N.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) No. & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Amount Alloted (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/19 20siwan- 2/08	Sarwar Gondi to Chilmaravan	31446602021	5139/24.09.19	3.750	125.909	76.24934	35.1832	184MBD of 2020-21/12.04.21	05.08.22	09.06.22	Good	25mm	5.032	74.04934	74.04934	1.38703	Complete
Total															74.04934	74.04934	1.38703	

प्रमाणित किया जाता है कि पथ में कराये गये कार्य के सभी अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन संबंधित कनीय अभियंता 50 प्रतिशत मापी का सत्यापन संबंधित सहायक अभियंता एवं 10 प्रतिशत मापी का सत्यापन अष्टाहस्ताक्षरी यथा कार्यपालक अभियंता द्वारा किया जा चुका है। कराया गया कार्य मानक एवं विशिष्टियों के अनुरूप है।

अभियंता
16/03/23
कनीय अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रखंड, सिवान-2

सहायक अभियंता
18/03/23
ग्रामीण कार्य विभाग,
कार्य प्रखंड, सिवान-2

प्रमुख लेखक/कार्यकारी
18/03/23
ग्रामीण कार्य विभाग,
कार्य प्रखंड, सिवान-2

कार्यपालक अभियंता
17.3.23
ग्रामीण कार्य विभाग,
कार्य प्रखंड, सिवान-2

FORM GFR 19-A(See Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate up to 15th March 2023**NEW MAINTENANCE POLICY (2018)**

PIU.....

Sl.No	Name of Scheme	Sanction No.& Date with Amount, (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under NEW MAINTENANCE POLICY (2018)	24/19.03.2020 59/18.08.2020 78/29.10.2020 82/13.11.2020 86/11.12.2020 05/12.01.2021 17/26.02.2021 20/19.03.2021 26/15.04.2021 52/24.08.2021 58/27.10.2021 60/09.11.2021 64/06.12.2021 68/23.12.2021 02/03.01.2022 05/25.01.2022 10/21.02.2022 18/11.03.2022 49/27.04.2022 01/20.05.2022 22/08.08.2022 35/13.10.2022 32/03.03.2023	309.44834 40.85500 127.93990 129.95438 140.17554 246.86987 257.50061 46.15519 70.50399 58.39236 177.05420 87.58854 1.27421 167.06400 614.19943 279.43486 11.26696 726.24067 29.31956 62.42914 272.11117 168.58187 604.61409	Certified that out of Rs 4371.47327 lacs received during the years 2022-23 in favour of Ex. Engineer, RWD, Works Division, siwan-2 Bihar, a sum of Rs 4106.82324 Lacs has been utilized for the purpose of NEW MAINTENANCE POLICY-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 264.65003 lacs remaining unutilized at the end of the period under.
	Total :		4371.47327	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3. **Physical Progress achieved :-**

- Construction of Road works.
- Construction of CD works.


DIVISIONAL ACCOUNT OFFICER
RURAL WORKS DEPARTMENT
WORKS DIVISION, SIWAN-2


EXECUTIVE ENGINEER
RURAL WORKS DEPARTMENT
WORKS DIVISION, SIWAN-2

17.3.23

Name of work : Sanwar Gondi - Chilmarwa

Name of customer : AMIT KUMAR CHATURVEDI

(R)Rural Road

Good

Average

Poor

< 4000

4001 - 5000

> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMPI/cm	Speed(Km/Hr)	Ultrasonic (mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
14/08/22	11:49:59	94	100	100	23.0 cm	13.1 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2107703	N	84.0666971	E	Normal
14/08/22	11:50:37	94	100	200	28.0 cm	19.0 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.2117243	N	84.0667810	E	Normal
14/08/22	11:51:18	94	100	300	36.0 cm	19.0 Km/Hr	3600.0 mm/Km	3507	4.63	Good	26.2125902	N	84.0669413	E	Normal
14/08/22	11:51:48	94	100	400	32.0 cm	12.1 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2133799	N	84.0671549	E	Normal
14/08/22	11:52:10	94	100	500	18.0 cm	16.0 Km/Hr	1800.0 mm/Km	1880	2.65	Good	26.2144098	N	84.0673685	E	Normal
14/08/22	11:52:50	94	100	600	13.0 cm	19.0 Km/Hr	1300.0 mm/Km	1428	2.08	Good	26.2146940	N	84.0680323	E	Normal
14/08/22	11:53:12	94	100	700	22.0 cm	16.3 Km/Hr	2200.0 mm/Km	2241	3.11	Good	26.2146692	N	84.0690470	E	Normal
14/08/22	11:53:33	94	100	800	23.0 cm	17.2 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2149954	N	84.0699701	E	Normal
14/08/22	11:53:56	94	100	900	25.0 cm	15.6 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2150774	N	84.0710306	E	Normal
14/08/22	11:54:20	94	100	1000	25.0 cm	15.0 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2150774	N	84.0720072	E	Normal
14/08/22	11:54:41	94	100	1100	23.0 cm	17.1 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2150602	N	84.0729990	E	Normal
14/08/22	11:55:02	94	100	1200	15.0 cm	17.6 Km/Hr	1500.0 mm/Km	1608	2.31	Good	26.2149992	N	84.0740442	E	Normal
14/08/22	11:55:24	94	100	1300	25.0 cm	15.7 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2146406	N	84.0747080	E	Normal
14/08/22	11:55:49	94	100	1400	31.0 cm	15.0 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2140303	N	84.0752802	E	Normal
14/08/22	11:56:17	94	100	1500	21.0 cm	12.7 Km/Hr	2100.0 mm/Km	2151	2.99	Good	26.2136164	N	84.0760279	E	Normal
14/08/22	11:56:58	94	100	1600	36.0 cm	18.9 Km/Hr	3600.0 mm/Km	3507	4.63	Good	26.2130213	N	84.0764322	E	Normal
14/08/22	11:57:28	94	100	1700	23.0 cm	16.6 Km/Hr	2300.0 mm/Km	2332	3.22	Good	26.2120905	N	84.0762720	E	Normal
14/08/22	11:57:47	94	100	1800	28.0 cm	19.4 Km/Hr	2800.0 mm/Km	2784	3.77	Good	26.2112226	N	84.0761042	E	Normal
14/08/22	11:58:07	94	100	1900	31.0 cm	17.4 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2102985	N	84.0759439	E	Normal
14/08/22	11:58:26	94	100	2000	30.0 cm	20.2 Km/Hr	3000.0 mm/Km	2864	3.99	Good	26.2093916	N	84.0757532	E	Normal
14/08/22	11:58:50	94	100	2100	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2874	3.88	Good	26.2086267	N	84.0759745	E	Normal

14/08/2022
14/08/2022

14/08/2022

14/08/2022

Name of work : Sarwar Gondi - Chilmanwa
 Name of customer : AMIT KUMAR CHATURVEDI

(R)Rural Road		
Good	Average	Poor
< 4000	4001 - 5000	> 5000


14/08/22	11:59:39	94	100	2200	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2078142	N	84.0780128	E	Normal
14/08/22	12:00:11	94	100	2300	27.0 cm	11.3 Km/Hr	2700.0 mm/Km	2893	3.88	Good	26.2089502	N	84.0781270	E	Normal
14/08/22	12:01:00	94	100	2400	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2084581	N	84.0783712	E	Normal
14/08/22	12:01:31	94	100	2500	33.0 cm	12.0 Km/Hr	3300.0 mm/Km	3236	4.31	Good	26.2058477	N	84.0787450	E	Normal
14/08/22	12:01:56	94	100	2600	31.0 cm	18.1 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2052336	N	84.0786918	E	Normal
14/08/22	12:02:19	94	100	2700	30.0 cm	17.1 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.2046804	N	84.0777521	E	Normal
14/08/22	12:02:45	94	100	2800	25.0 cm	18.2 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2039156	N	84.0779505	E	Normal
14/08/22	12:03:16	94	100	2900	30.0 cm	20.2 Km/Hr	3000.0 mm/Km	2964	3.99	Good	26.2093916	N	84.0757532	E	Normal
14/08/22	12:03:50	94	100	3000	29.0 cm	15.6 Km/Hr	2900.0 mm/Km	2874	3.88	Good	26.2086267	N	84.0759745	E	Normal
14/08/22	12:04:09	94	100	3100	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2078142	N	84.0760126	E	Normal
14/08/22	12:04:43	94	100	3200	27.0 cm	16.3 Km/Hr	2700.0 mm/Km	2893	3.86	Good	26.2089502	N	84.0761270	E	Normal
14/08/22	12:05:12	94	100	3300	32.0 cm	17.2 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2084581	N	84.0763712	E	Normal
14/08/22	12:05:49	94	100	3400	33.0 cm	16.0 Km/Hr	3300.0 mm/Km	3236	4.31	Good	26.2058477	N	84.0767450	E	Normal
14/08/22	12:06:16	94	100	3500	31.0 cm	14.1 Km/Hr	3100.0 mm/Km	3055	4.09	Good	26.2052336	N	84.0769918	E	Normal
14/08/22	12:06:55	94	100	3600	32.0 cm	15.1 Km/Hr	3200.0 mm/Km	3145	4.2	Good	26.2046804	N	84.0777521	E	Normal
14/08/22	12:07:11	94	100	3700	25.0 cm	14.2 Km/Hr	2500.0 mm/Km	2512	3.44	Good	26.2039156	N	84.0779505	E	Normal

Signature
 14/08/22
 S.B

Signature
 14/08/22
 A.E

Signature
 14/08/22

Name of Customer: AMIT KUMAR CHATURVEDI, Machine no: 19208, Road: Sarwar Goudi - Chilmantra, Date: 14-08-22, Section No: 94, Equation: $Y=0.904X+252.3$



[Signature]
14/08/22
A.C.

[Signature]
14/08/22
A.C.

[Signature]
14/8/22