

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 434...../बक्सर

दिनांक- 20/03/23.....

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

प्रसंग :- विभागीय पत्रांक- 1762 दिनांक- 20.03.2023
महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


20/03/23
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

AK
20/03/23

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054)

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	File. No.- 13/EIC-01-06/2021, dt.- 10.02.2021	136.03240	Certified that out of Rs. 136.03240 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 133.96705 lacs has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs 2.06535 lacs remaining unutilized at the end of the period under

Total -

- 2 Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road works
- Construction of CD works

D.A.O.
R.W.D. (w) Div. Buxar


12.03.23
Executive Engineer
R.W.D. (w) Div. Buxar

17/03/23

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

SI No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in KM)	Amount (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)									
1	RM/BU/BU X/22/0001	CHAMILLA TO INTALUNHA VIA MANGOLPUR ROAD	10401912009	Letter No 852 & 18/02/2022	3.600	140.59	62.68138	27.85769	10/MBD/2022-23 & 30.11.2022	29.08.2023	2693	25 mm	5.00%	56.8819	56.69883	4.44906	
2	RM/BU/BU X/22/0001	BUXAR DHANSOI BASWAN KALA ROAD TO BRADIIH AUR GOPPUR	10401913006	Letter No 852 & 18/02/2022	3.500	156.47	74.08954	30.04877	10/MBD/2022-23 & 30.11.2022	29.08.2023	2980	25mm	5.01%	62.1319	61.18499	4.07634	
3	RM/BU/BU X/22/0001	Dhansoi Chousa Road to Chibbili Road Via Kaitima H.S.	10401901009	Letter No 852 & 18/02/2022	3.500	152.47	81.7235	30.6694	10/MBD/2022-23 & 30.11.2022	29.08.2023	2955	25mm	5.01%	0	0	79.39692	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS

17.03.23
Executive Engineer
RWD (W), Div.- Buxar


17/03/23

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स....415..... बक्सर/ दिनांक.....17/03/23.....

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Chausa Dhansoi Road to Kaithna High School to Chilbila Siwan पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।

 16/03-23


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा बक्सर

 17/03/23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : E:\maatarachandi 3\16031905.Xls. Section No. : 6. Eqn : test

Name of Customer : Maa Tarachandi Construction, Name of Work/ Road : Chausa Dhansoi road to Kaithna High



18/03/23

20/03/23

Name of Road:- Chausa Dhansol Road Kaithna High School To Chilbila Siwan Contractor's Name:- Maa Tarachandi Construction

Date	Time	Section	No.	Length in km	Bumps in mm	Rate	Speed	OR	IRI, TEGORY	Latitude	ongitude	Event
20/3/23	15:23:5	6	0.1	220	10.1	2200	2631 G	25.40343	83.99258 Normal	Y = 0 * X ^ 2 + 1.136 * X + 132.5		
20/3/23	15:24:40	6	0.1	230	10.1	2300	2745 G	25.40248	83.99266 Normal	X = 3261		
20/3/23	15:26:0	6	0.1	260	10.1	1800	2256 G	25.40156	83.99269 Normal	Y = 3836		
20/3/23	15:27:16	6	0.1	210	10.1	2100	2518 G	25.40114	83.99197 Normal			
20/3/23	15:28:0	6	0.1	190	10.1	1900	2290 G	25.40105	83.99098 Speed Breaker			
20/3/23	15:29:1	6	0.1	190	10.1	1900	2290 G	25.40094	83.98993 Normal	(R) RURAL ROAD		
20/3/23	15:29:37	6	0.1	230	10.1	2300	2745 G	25.40001	83.98992 Normal	Good	Average	Poor
20/3/23	15:30:05	6	0.1	250	10.1	2500	2972 G	25.39906	83.98992 Normal	<4000	4001-5000	>5001
20/3/23	15:30:56	6	0.1	310	10.1	2300	2597 G	25.39813	83.98992 Normal	IRI Value=2955		
20/3/23	15:31:0	6	0.1	260	10.1	2200	2489 G	25.39715	83.98993 Normal	Machine ID=415		
20/3/23	15:32:23	6	0.1	230	10.1	2300	2745 G	25.39626	83.98992 Normal			
20/3/23	15:33:00	6	0.1	260	10.1	1800	2369 G	25.39528	83.98992 Normal			
20/3/23	15:33:56	6	0.1	320	10.1	2600	2967 G	25.39434	83.98992 Normal			
20/3/23	15:34:33	6	0.1	340	10.1	2800	2810 G	25.39344	83.98993 Normal			
20/3/23	15:35:12	6	0.1	330	10.1	1700	1985 G	25.39249	83.98997 Normal			
20/3/23	15:36:44	6	0.1	260	10.1	1500	1968 G	25.39154	83.99007 Normal			
20/3/23	15:37:12	6	0.1	250	10.1	2500	2972 G	25.39161	83.98909 Normal			
20/3/23	15:38:5	6	0.1	380	10.1	1900	2272 G	25.39171	83.98808 Normal			
20/3/23	15:39:45	6	0.1	280	10.1	1900	2256 G	25.39167	83.98712 Normal			
20/3/23	15:40:12	6	0.1	350	10.1	2100	2456 G	25.39181	83.98613 Normal			
20/3/23	15:41:16	6	0.1	300	10.1	1800	2182 G	25.39195	83.98508 Normal			
20/3/23	15:42:0	6	0.1	290	10.1	1400	1689 G	25.39164	83.98448 Normal			
20/3/23	15:43:05	6	0.1	350	10.1	1700	2109 G	25.39074	83.98423 Normal			
20/3/23	15:44:0	6	0.1	230	10.1	2300	2745 G	25.39024	83.98365 Normal			
20/3/23	15:45:22	6	0.1	190	10.1	1900	2290 G	25.39055	83.98269 Normal			
20/3/23	15:46:0	6	0.1	300	10.1	3000	3540 G	25.39071	83.982 Normal			
20/3/23	15:47:19	6	0.1	240	10.1	2400	2858 G	25.39099	83.98084 Normal			
20/3/23	15:48:0	6	0.1	310	10.1	1800	2285 G	25.39097	83.97987 Normal			
20/3/23	15:49:29	6	0.1	400	10.1	1800	2259 G	25.39006	83.98 Normal			
20/3/23	15:50:03	6	0.1	310	10.1	1800	2678 G	25.38931	83.97958 Normal			
20/3/23	15:51:00	6	0.1	370	10.1	1200	1685 G	25.38837	83.97975 Normal			
20/3/23	15:52:40	6	0.1	340	10.1	2200	2685 G	25.38746	83.97995 Normal			
20/3/23	15:53:15	6	0.1	430	10.1	1800	2109 G	25.38655	83.9801 Normal			
20/3/23	15:54:16	6	0.1	150	10.1	1900	1659 G	25.38606	83.98013 Normal			
20/3/23	15:55:09	6	0.1	150	10.1	1900	1769 G	25.38603	83.98015 Normal			

20/3/23
19:03:23

20/3/23