

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, दानापुर।

पत्रांक:- 369 अलु

दानापुर/दिनांक:- 21/03/23

प्रेषक :

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल दानापुर।

सेवा में,

सचिव ब्राडा (बी.आर.आर.डी.ए.)
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:- शीर्ष-3054 (एम.आर.) बिहार ग्रामीण पथ नई अनुरक्षण नीति-2018 योजना
अंतर्गत अनुरक्षण मद में आवंटन के अधियाचना के सम्बन्ध में।


महाशय,


उपर्युक्त विषय के संबंध में कहना है कि शीर्ष-3054 (एम.आर.) बिहार
ग्रामीण पथ नई अनुरक्षण नीति-2018 योजना अंतर्गत अनुरक्षण मद में निम्नांकित पथों का
आवंटन के अधियाचना का मांग (Yearly Quarter Wise) तैयार कर आवश्यक
कार्रवाई हेतु समर्पित की जा रही है जो निम्न प्रकार है।

अतः अनुरोध है कि उक्त योजना
अन्तर्गत अनुरक्षण मद में आवंटन उपलब्ध कराने की कृपा की जाये ताकि संवेदक का
भुगतान किया जा सके।

(यथोक्त)

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल दानापुर।



<u>Sl.No</u>	<u>Name of The Road</u>	<u>Yearly Quarter Wise</u>	<u>Amount (In Lakh)</u>
1.	Khagaul Naubatpur Road To Korra (Pkg.No-RM/PA/DAN/20/0011)	1 st Year- 1 st Quarter	1.00610
		1 st Year- 2nd Quarter	1.00610
2.	NH-98 To Gali (Road) No-2 Brindawan Colony (Pkg.No-RM/PA/DAN/20/0011)	1 st Year- 1 st Quarter	0.12508
		1 st Year- 2nd Quarter	0.12508
3.	NH-98 To Nausa (Pkg.No-RM/PA/DAN/20/0011)	1 st Year- 1 st Quarter	0.16854
		1 st Year- 2nd Quarter	0.16854

Handwritten signature
17/12/23

Handwritten signature
21/12/23

Handwritten signature
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दानापुर
21/3/23

Name of The Road:- NH-98 Gali (Road) No-2 Brindawan Colony

Package No:- MR/N/19-20-Danapur/11

Total Length:- 0.575 Km

Block: Fulwarisharif

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event			
11/1/23	11:13:18	17	0.1	390	0	3900	3928	G	25.545373	84.973518	Cure	$Y = 0 \cdot X^4 + X^3 + 278.4$		
11/1/23	11:13:18	17	0.1	390	30.3	3900	3928	G	25.54614	84.973602	Normal	$Y = 6.285$		
11/1/23	11:13:18	17	0.1	360	30.3	3600	3648	G	25.54701	84.973922	Normal	(R) RURAL ROAD		
11/1/23	11:14:0	17	0.1	380	20.2	3800	3712	G	25.547835	84.974308	Normal	Good	Average	Poor
11/1/23	11:14:0	17	0.1	350	30.3	3500	3554	G	25.54864	84.97441	Normal	<4000	4001-5000	>5001
11/1/23	11:14:0	17	0.075	380	20.2	3800	3712	G	25.54558	84.972515	Normal			
TOTAL			0.575	2250	131.300	22500	22482							
AVERAGE						3750	3747							

11/1/23
11:14:0
17


कर्मचारीक अभियंता
प्रमाणित करने विभाग
दरवा प्रमंडल, सहायक

Name of Customer:	M/S. Arjan Construction
Name of Work/ Road:	14H-98 To Gail Road No-2 Bw
Lab Job number:	
Date:	11-01-2023
Section No.	30

Test Date:	11-01-2023	Road Name:	14H-98 To Gail Road No-2 Bw
Machine No:	374	Road Type:	(N) RURAL ROAD
Start S No:		Side:	
Start E No:		Interval	
Weather:		UV Range:	2554 To 5000 mm/Am
Start Location:		Dial Range:	0 To 0.7 0.1 1000 m
End Location:		Equation:	$Y = 0 \cdot X^2 + 0.936 \cdot X + 278.4$

Print Generate Report and Graph

File > Online Maintenance Requisition Package No-11/250/1612 Xls, Section No-30, Eqn: $Y = 0 \cdot X^2 + 0.936$
 Name of Customer: M/S. Arjan Construction, Name of Work/ Road: 14H-98 To Gail Road No-2 Bhandawa Colony.



11/01/2023

11/01/2023

कोचवालक अभियंता
 ग्रामीण कर्म विभाग
 कोच वालवाल, रायपुर

Requisition Format for Scheme Head-MR-(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division, Danapur
Government Of Bihar

1st Year (2nd Quarter)

OM01

Rural Works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From:- NH-98 To Gail (Road) No-2 Brindawan Colony
(Package No:- RM/P4/DAN/20/0011
Length of Road :- 0.575 Km
Inspector :- J.E RWD Sub Division : Fulwari Shafit

To:-

Executive Engineer
RWD, Works Division, Danapur

Position :- J.E

No	Standard of Work Item	Work Unit	1	2	3	4	5	6	7	8	9	10	Comments
OM100	Sealed payment												Comments
OM101	Pothole Patching	m ²											No Pot Hole found.
OM102	Surface Depression and Rut Patching	m ³											Not Surface Depression & Rut Patching Found
OM103	Crack Sealing	Lm											No Crack found
	Surface Treatment												
OM104	(a) Loss of Aggregate (Surface Ravelling)	m ²											No loss Of Aggregates (Surface Ravelling) Found
	(b) Bleeding / Flushing @ Crocodile Cracking	m ²											No Bleeding/ Flushing Required
105	Edge Repair	m ²											No Crocodile Cracking Found
106	Digouts	m ²											No Edge Repair Required
107	Concrete pavement	m ³											Not Required
	Other activities												N/A
OM200	Shoulder												
	Unsealed Shoulder												
OM201	(a) Edge Drop-off	Lm											No Edge Drop-Off Required
	(b) Roughness, Scouring or Potholes	Lm											No Roughness, Scouring or Potholes Found
	(c) Holding water	Lm											No Holding Water Found
OM202	Embankment Repair	M ³											Repaired as required
	Other activities (Rain Cuts)												N/A
OM300	Drainage Including Culverts major	Lm											N/A
OM301	Surface Drains & Verge	No											Cleaned
OM302	Culvert Cleaning	M ³											Not Required
OM303	Culvert and Pot Repair	M ²											Not Required
	Other activities (While washing)	M ²											

No	Standard of Work Item	Work Unit	1	2	3	4	5	6	7	8	9	10	Comments
OM400	Vegetation	Unit											
	Grass Control												
	(a) Roadside-General Tidy	Ha	Nil										Not Required
OM401	(b) Clear near Safety signs, kilometre posts and road side furniture	Ha	Nil										Not Required
	Tree and Shrub Management	No	Nil										Not Required
OM402	Cutting of Branches of Trees	No	Nil										Not Required
	Cutting of Shrubs From Road Way	No	Nil										Not Required
	Other activities (Trimming of Grass)	M ²	Nil										Not Required
OM500	Safety Signage and Road	No	Nil										Not Required
OM501	Signs Maintenance	No	Nil										Maintained
OM502	Guard Stones	Ln	N/A										Maintained
OM503	Distance Stones	No	N/A										Maintained
OM504	Road Marking	M ²	Nil										N/A
	Other activities												

15/01/23
At

Executive Engineer
Rural Works Department
Works Division, Danapur

STANDRAD FORMAT FOR ROADS QUARTERLY STATEMENT

1	Name of the Road-	NH-98 To Gali (Road) No-2 Brindawan Colony		
2	Batch No.-	RM/PA/DAN/20/0011		
3	Project ID -	1121035022		
4	Total Length of Road (in Km)	0.575		
5	Length of Road to Meet Required Service Level [Completed length] (in Km) (1)	0.575		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule (Agreement Amount for Maintenance) (in Lakh)	2.50150		
8	Quarterly Payment :2/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) (2)	0.12508		
Compliance Criteria	Standard Job Description	Non-Compliant		Reduction Payment (6) = (3) / (1) * (2) * (4)
		Length Non Compliant (3)	Weighted Value for Payment Reduction (%) (4)	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0.00000
II	SHOULDERS AND EMBANMENTS	0	10%	0.00000
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0.00000
IV	SIGNAGE AND ROAD SAFETY	0	10%	0.00000
V	VEGATAION		5%	0.00000
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in Lakh) [5]				0.00000
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				0.12508

Date of inspection by E/I or his agent

Date

Signature of person inspecting road

Name and Designation of person inspecting road

Certify by E/I (Signature) Date