

24

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work done:- Repairing boundary wall & roof from 1063-702 to Dyaneshpur under new me mistry 2018.					
At Brothers Building					
At northward pur, Somapuri-					
med no: 06 MBD / 2023-24					
of Commenced: 15.5.2023					
of completion: 14.02.2024					
Intake done					

[illegible]

Scanned with CamScanner

② Planting of tree - do

- do -

= 208' 0" - work term (29)

③ 1201.80 / day ————— & 249912' ✓

④ Pick fruiting log band - do

= 3.0 day - work term (29)

⑤ 11686.52 / day ————— & 35059' ✓

= 18008500' ✓

Add 8.1% cost = 3241530' ✓

Add 1% L. log = 180085' ✓

Add S.F. = ~~167805' ✓~~
~~173090' ✓~~

= 21537920' ✓

Less 0.63% - 136067' ✓

Π Continuation = 21461853' ✓

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B/F H - 21 46/853w
less primary payment					= 38 300 60w
					= 133 442 22w
					= 428 757 1w
Drum					
14.9.23					
22/09/23					
OR					
Chf					
28.09.23					
					Cost high sheet
					work completed
					as per specification.
					Drum
					14.9.23