

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, झाझा।

पत्रांक 1428(अनु०)।

झाझा

दिनांक 08/11/23।

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल- झाझा।

सेवा में,

नोडल पदाधिकारी
नई अनुरक्षण नीति 2018(MR 3054)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय:- शीर्ष नई अनुरक्षण नीति 2018(MR 3054) अंतर्गत अनुरक्षण मद में राशि की अधियाचना के संबंध में।

महाशय ,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष नई अनुरक्षण नीति 2018(MR 3054) अंतर्गत अनुरक्षण मद में कार्य की अद्यतन स्थिति के अनुसार अधियाचना वाछित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

अतः अनुरोध है कि आवंटन विमुक्त करने की कृपा की जाय ताकि संवेदक को ससमय भुगतान की जा सके।


अनु०:-यथोक्त।

विश्वास भाजन


8/11/23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल झाझा।


8/11/23


8/11/23

RWD Works Division, Jhajha (Dist :- Jamui)

Requisition Format for Scheme Head- MR (3054) Under Bihar Rural Road " New Maintenance Policy 2018" (Initial Rectification and Surface Renewal)

Name of Division:- Jhajha

S.N	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (A.A) Letter No. & Date	Administrative Approval (A.A)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI in MM/KM	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content (in %)	Previous Total Allowed Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (K.M)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RN/A/JHA /22/0014	L157-L080 To koria	20804202180	754 & 26.07.2022	1.638	90.289	68.68483	22.54216	26/MBD/MR-N/2022-23	05.10.2023	28.10.2023	2441	25	5.00	0.00000	0.00000	67.78039	Surface Completion
2	RN/A/JHA /22/0014	L070-ghumari To Daridih	20804202127	754 & 26.07.2022	1.33	72.738	54.42519	16.76217	26/MBD/MR-N/2022-23	05.10.2023	17.10.2023	2298	25	5.01	0.00000	0.00000	47.88391	Surface Completion
3	RN/A/JHA /22/0004	L117-Harimadhi To Karamanur	20804202162	26 & 26.05.2022	1.5	104.685	84.4034	18.37082	23/MBD/MR-N/2022-23	06.10.2023	04.10.2023	2604	25	5.00	0.00000	0.00000	83.93186	Surface Completion
4	RN/A/JHA /23/0003	Giddahur Mauna REO Road via Utkramit Middle School, Palsanda More to Kandhaura Road.	20804201004	754 & 26.07.2022	1.2	70.996	52.65089	8.90597	24/MBD/MR-N/2022-23	19.11.2023	02.11.2023	3303	0	0	0.00000	0.00000	51.99535	PCC in Whole length
5	RN/A/JHA /23/0006	Jamui Chakki PWD Road of Bandah more to Bandah Chhitrpathal Chaupha Road	20804208039	31.03.2023	6.78	650.775	463.65303	126.00532	07/MBD/MR-N/2023-24	27.04.2024	07.11.2023	2202	25	5.00	0.00000	0.00000	461.42674	Surface Completion

[Signature]
8.11.23

[Signature]
8/11/23
Executive Engineer
RWD Works Division, Jhajha

Sl. No.	Name of Scheme	Sanction No. & Date with	Amount Received (in Lacs Rs.)	Particulars
1.	Construction of Rural Roads under New Maintenance Policy 2018 (MR3054)	Letter No-147 Dated- 01.11.2023	11219.42215	Certified that out of Rs. 11219.42215 Lakhs received upto the years 23-24 in favour of Ex. Engineer, RWD Bihar, Jhajha a sum of Rs 11014.89672 lakhs has been utilized for the purpose of New Maint. Policy 2018 (MR3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs 204.52543 lakhs remaining unutilized at the end of the period .
	Total		11219.42215	

2. Certified that I have satisfied may self that the conditions on which the grants in and was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised-

- Works have been supervised by Executive Engineer/Superintending Engineer
 - Periodical inspection has been conducted by Executive engineer/Superintending Engineer
 - Construction materials have been tested.
 - Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer
 - All other codal formalities have been observed.
3. Physical Progress achieved-
- i. Construction of Road Works Construction of C.D. Works .

2000
23.11.23


8/11/23
Executive Engineer
RWD(w) Div. Jhajha

1. 2021.11.17-Harijaindhi To Karmatanr

$$y = 0 \cdot x^2 + 0.828 \cdot x + 341.6$$
$$X = 10000$$
$$Y = 2621$$

(R) RURAL ROAD

	Good	Average	Poor
1. The company's financial performance is strong	4.5	3.5	2.5
2. The company's financial performance is average	3.5	3.5	2.5
3. The company's financial performance is poor	2.5	3.5	2.5
4. The company's financial performance is very poor	1.5	3.5	2.5
5. The company's financial performance is very strong	4.5	3.5	2.5

4001-5000 >5001

Name of Agency-Amrendra Kumar Atri Infrastructure Private Limited											
Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
2/11/23	10:0:15	98	0.1	210	10.1	2100	2080	G	24.568278	86.421852	Normal
2/11/23	10:1:35	98	0.1	180	10.1	1800	1831	G	24.568278	86.42308	Normal
2/11/23	10:1:56	98	0.1	180	10.1	1800	1831	G	24.568532	86.424107	Normal
2/11/23	10:4:35	98	0.1	190	10.1	1900	1914	G	24.566127	86.427305	Normal
2/11/23	10:5:10	98	0.1	300	10.1	3000	2825	G	24.56527	86.427172	Normal
2/11/23	10:5:25	98	0.1	290	10.1	2900	2742	G	24.56442	86.426868	Normal
2/11/23	10:6:0	98	0.1	280	10.1	2800	2659	G	24.563658	86.426397	Normal
2/11/23	10:6:20	98	0.1	320	10.1	3200	2991	G	24.562845	86.425925	Normal
2/11/23	10:6:55	98	0.1	290	10.1	2900	2742	G	24.561952	86.425673	Normal
2/11/23	10:7:31	98	0.1	210	10.1	2100	2080	G	24.561792	86.42648	Normal
2/11/23	10:8:6	98	0.1	170	10.1	1700	1749	G	24.561862	86.42749	Normal
2/11/23	10:11:2	98	0.1	350	10.1	3500	3239	G	24.562342	86.428298	Normal
2/11/23	10:11:38	98	0.1	330	10.1	3300	3073	G	24.562802	86.42914	Normal
2/11/23	10:12:13	98	0.1	390	10.1	3900	3570	G	24.563198	86.43	Normal
2/11/23	10:16:0	98	0.1	410	10.1	4100	3736	G	24.563162	86.430353	Normal

[Signature]
8/11/23
Executive Engineer
Rural Works Department
Works Division, Bhajjala

22/11/23

Name of Customer : Aravinda Kumar Ahi Indira

Name of Work/ Road : [117] Mandya To Karmelam

Lab Job number : 98

Date : 11/2/2023


Section No. : 98

Print Generate Report and Graph

Test Date :	<u>11/2/2023</u>	Road Name :	<u>[117] Mandya To Karmelam</u>
Machine No :	<u>435</u>	Road Type :	<u>(R) RURAL ROAD</u>
Start S No :		Side :	
Start E No :		UTV Range :	<u>7.7</u> To <u>50000</u> <u>mm/km</u>
Weather :		Dist Range :	<u>0</u> To <u>15</u> <u>0.1</u> <u>1000 m</u>
Start Location :		Equation :	<u>$Y = 0.0 \cdot X^2 + 0.028 \cdot X + 341.8$</u>
End Location :			

Redraw Graph Map View

Name of Customer : Name of Work/ Road : Lab Job number : Section No. 98, Eqa. $Y = 0.0 \cdot X^2 + 0.028 \cdot X + 341.8$



Aravinda
Executive Engineer
Rural Works Department
11/11/23

CHAKRA

MR-N/22.23/5454/03

Schedule XLV From No. 134.
BIHAR P. W.D.

HARRISDH1 TO KARMATARA. DIVISION

23/MBD/HR-N/2022-23 SUB-DIVISION

MEASUREMENT BOOK

AMRENDRA KR. INFRA TRK WRC. PVT. LTD

1388

Name of work :

Situation of Work.

Agency by which work is executed.

Date of measurement.

No. and date of agreement

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
Name of work - Harjandhi Tu					
Korralam and w MK305					
Name of Agency - Amrendra Kumar					
Ami					
Ag. No - 23/MKD/MR-N/2022-23					
Date of start - 7/1/23					
Time of completion - 6/10/23					
Date of Measurement - 3/10/23					

		1600mm		
(1)	Earth work in excavation in foundation do -			
	do as per plan			
H/Wall	$2 \times 2 \times 6.45 \times 1.4 \times 1.50 = 54.18 m^3$			
Below Pipe	$2 \times 1.85 \times 1.50 \times 6.75 = 11.13 m^3$			
	$= 65.31 m^3$			
(2)	ply RCC MS in above foundation do -			
	do as per plan			
H/Wall	$2 \times 2 \times 6.45 \times 1.4 \times 0.15 = 5.41 m^3$			

A blank sheet of white paper featuring a black grid pattern. The grid consists of 6 columns and 8 rows of squares. The lines are slightly irregular, suggesting it was hand-drawn or scanned from a physical document. There are some faint smudges and marks on the paper, particularly along the horizontal lines.