

**कार्यपालक अभियंता का कार्यालय**  
**ग्रामीण कार्य विभाग, कार्य प्रमंडल, पीरो (भोजपुर)**  
**पत्रांक 2233 / पीरो दिनांक 08.11.2023**

प्रेषक,

कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल पीरो, भोजपुर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी  
सह-सचिव, ब्राडा  
ग्रामीण कार्य विभाग  
बिहार, पटना।

विषय:- योजना शीर्ष बिहार ग्रामीण पथ अनुरक्षण नीति-2018 (मरम्मत कार्य)  
एम0आर0 के तहत पथों की अधियाचना के संबंध में।



महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि योजना शीर्ष बिहार ग्रामीण पथ अनुरक्षण नीति-2018 (मरम्मत कार्य) एम0आर0 के अंतर्गत प्रमंडल में चल रहे कार्य के मद में भुगतान हेतु संलग्न प्रपत्र में आवंटन की अधियाचना की गई है।

अतः अनुरोध है कि कुल 23.16462 लाख (तेईस लाख सोलह हजार चार सौ बासठ) मात्र आवंटन उपलब्ध कराने की कृपा किया जाय, जिससे संवेदक का भुगतान किया जा सके।

अनु0-**यथोक्ता**

विश्वासभाजन

  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल पीरो, भोजपुर  


# Requisition Format for Scheme Head - 5 Year Maintenance of MR(3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and surface

Name of Division :- Piro

Name of Circle :- Ara

Sl. No	Name of Road	Batch No	Project ID as per MIS	Administrative Sanction Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (DD/MM/YYYY)	IRI As per bump Report	Current Maintenance Demand (in Lacs)				Total	Remarks.
					Length (in km)	Amount of (in Lakh)	Initial Rectification with surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)					1st Qtr Maint Demand	2nd Qtr Maint Demand	3rd Qtr Maint Demand	4th Qtr Maint Demand		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	Improvement of Hsan Bazar Tateardih kutana Road	RM/BH/TPR /19/0002	10401604122	2012/02.07.2019	1.75	40.5	36.128	12.99601	08/M.B.D /MR-2019-20	31.01.2020	10/11/2020	3014	0.64980	0.64980	0.64980	0.64980	2.54920	Completed
2	Amhata Pul to Barpur Siwat Via Ganpat Tola Sainkhana, suryapur Tola Budhram tola	RM/BH/TPR /19/0002	14181031840		7.6	206.51	124.607	53.96596		31.01.2020	10/11/2020	3070	2.69830	2.69830	2.69830	2.69830	10.79320	Completed
3	Construction of Road from Sahayana at Ara Sasaram main road to Baisadih	RM/BH/TPR /19/0002	10401801008		2.9	81.33	48.484	21.48596		31.01.2020	10/11/2020	3082	1.07430	1.07430	1.07430	1.07430	4.29720	Completed
4	Chak Tola - Bechena More Path via Pilua Tola, Lakhen Tola & Ranjan	RM/BH/TPR /19/0002	NEA220001630		7.415	213.03	128.846	54.75013		31.01.2020	1/4/2021	3066	2.73751	2.73751	0.00000	0.00000	5.47502	Completed
21.16462																		

*Pradyumn Kumar*  
8-11-23

**D.A.O.-1**

R.W.D. Works Division Piro (Bhojpur)

*8/11/23*  
**Executive Engineer**  
R.W.D Work Division  
Piro

**FORM GFR 19-A****(See Government of India's Decision (1) below Rule-150)****Form of utilisation Certification up to month of UPTO 08.11.2023****MR (3054) Under Five Year Routine Maintenance Bihar Rural Road  
Maintenance Policy-2018 (Maintenance)****R.W.D. Works Division-Piro (Bhoipur)**

SL. NO.	Name of Scheme	Sanction No & Date with Amount (In Rs. Lacs)	Amount Received (In Rs. Lacs)	Particulars
1.	Maintenance of Rural Road under MR (3054) Under Five Year Routine Maintenance Bihar Rural Road Maintenance Policy-2018 (Maintenance)	Secretary cum Empowered officer B.R.R.D.A Let. No.- Dt.-	230.65684	Certified that out of Rs <b>230.65684</b> Lacs of grant in aid received during the Year <b>2023-24</b> in favour of Executive Engineer RWD Bihar <b>R.W.D. (W), Div, Piro</b> A sum of Rs <b>205.67862</b> Lacs has been utilized for the purpose of MR (3054) Under Five Year Routine Maintenance Bihar Rural Road Maintenance Policy-2018 (Maintenance) Schemes as given in the margin for which it was sanctioned and that the balance of Rs <b>24.97822</b> Lacs remaining unutilized at the end of the period under.
		<b>Total</b>	<b>230.65684</b>	

2. Certified that I have satisfied myself that the conditions on which the grants-in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


**Kind of Checks exercised:-**

- VII. Works have been supervised by Executive Engineer/ Superintending Engineer.
- VIII. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- IX. Construction material have been tested.
- IV. Measurements have been recorded in the MBS and test check conducted by the Assistant Engineer/Executive Engineer.
- V. All other codal formalities have been observed.

**3. Physical progress achieved:**

- i. Construction of Road Works.
- ii. Construction of CD Works.

  
**Divisional Accounts Officer  
R.W.D.(W) Div, Piro**

  
**Executive Engineer  
R.W.D.(W) Div, Piro**

Name of Road : Improvement of Hsan Bazar Tateardih Kataria Road, Contractor Name - Bishnu Shankar Ojha

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
1/11/2023	10:55:03	61	0.1	270	12.3	2700	3168	G	25.272285	84.35042	Speed Breaker
1/11/2023	10:55:13	61	0.1	290	40.4	2900	3364	G	25.2727	84.349578	Curve
1/11/2023	10:55:23	61	0.1	280	30.3	2800	3266	G	25.273472	84.349865	Normal
1/11/2023	10:55:39	61	0.1	260	30.3	2600	3069	G	25.274365	84.349998	Normal
1/11/2023	10:55:49	61	0.1	250	40.4	2500	2971	G	25.275223	84.350218	Normal
1/11/2023	10:55:55	61	0.1	260	40.4	2600	3069	G	25.275992	84.350588	Curve
1/11/2023	10:56:00	61	0.1	250	30.3	2500	2971	G	25.276925	84.350773	Normal
1/11/2023	10:56:14	61	0.1	270	20.2	2700	3168	G	25.277787	84.350858	Normal
1/11/2023	10:56:34	61	0.1	280	10.1	2800	3266	G	25.278665	84.350807	Curve
1/11/2023	10:57:00	61	0.1	250	10.1	2500	2971	G	25.278573	84.349915	Normal
1/11/2023	10:57:10	61	0.1	270	20.2	2700	3168	G	25.278715	84.348838	Normal
1/11/2023	10:57:25	61	0.1	260	20.2	2600	3069	G	25.27885	84.347862	Normal
1/11/2023	10:57:35	61	0.1	270	20.2	2700	3168	G	25.279035	84.348918	Normal
1/11/2023	10:57:40	61	0.1	290	30.3	2900	3364	G	25.279108	84.345975	Normal
1/11/2023	10:58:00	61	0.1	280	30.3	2800	3266	G	25.27952	84.345252	Normal
1/11/2023	10:58:20	61	0.1	260	30.3	2600	3069	G	25.280407	84.345572	Normal
1/11/2023	10:58:30	61	0.1	270	30.3	2700	3168	G	25.28115	84.345842	Normal
1/11/2023	10:58:42	61	0.05	140	30.3	2800	3266	G	25.281135	84.345555	Normal
Total Length			1.75	Average:				3157			

$$Y = 0 * X^2 + 0.984 * X + 510.7$$

$$X = OR$$

$$Y = 510.70$$

( R ) RURAL ROAD

Good      Average      Poor  
 <4000      4001-5000      >5001

Saxi  
 11/11/23  
 Junior Engineer  
 Rural Works Department  
 Works Division, Piro


G.K.  
 11/11/23  
 Assistant Engineer  
 Rural Works Department  
 Works Division, Piro

2MA  
 12/11/23  
 Executive Engineer  
 Rural Works Department  
 Works Division, Piro



File:C:\Users\De\l\Desktop\Hasan Bazar Tetardih Katariya Road, Length- 1.800 km\Hasan.xls, Section No.: 61

Name of Customer : Vishnu Shankar Ojha, Name of Work/ Road : Hasan Bazar Tetardih Katariya Road, Lab Job Number :



Saj  
11/11/23  
Junior Engineer  
Rural Works Department  
Works Division, Piro

Gak  
01-11-2023  
Assistant Engineer  
Rural Works Department  
Works Division, Piro

Amk  
02/11/23  
Executive Engineer  
Rural Works Department  
Works Division, Piro

# STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name :- RWD, Works Division, Piro

4th Quarter

1	Name of the Road	Improvement of Hsan Bazar Tateardih Kataria Road		
2	Batch No.	RM/BH/PIR/19/0002		
3	Project ID	10401604122		
4	Total Lenth of Road (in KM)	1.75		
5	Length of Road to Meet Required Service Level [Completed length](in Km) [1]	1.75		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	12.99601		
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	0.64980		
Compliance Criteria	Standard Job Description	Non-Compliance		Reduction Payment [6]=[3]/[1]*[2]*[4]
		Length Non- Compliant [3]	Weighted Value for Payment Reduction (%)[4]	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0.00
II	SHOULDERS AND EMBANMENTS	0	10%	0.00
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0.00
IV	SIGNAGE AND ROAD SAFETY	0	10%	0.00
V	VEGATION	0	5%	0.00
<b>TOTAL PAYMENT REDUCTION FOR THE QUARTER (IN Lakh) [5]</b>				<b>0.00000</b>
<b>TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]</b>				<b>0.64980</b>

Date of inspection by E/I or his agent  
Prepare by Contractor's self Control unit

Sep  
11/11/23  
J.E

Name and Designation of person inspecting road

Date 01/11/2023

(Signature)

Gak  
01/11/2023

Signature of person inspecting road

24/8  
02/11/23

Certify by E/I [signature] Date:-  
Executive Engineer  
Rural Works Department  
Works Division, Piro

4th Quarter

Rural Works Department

## SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

 RWD, Works Division Piro  
 Government Of Bihar  
 OM01

 Road From :- **Improvement of Hsan Bazar Tateardih Kataria Road**

Position :- A.E.

Length of Road :- 1.75 KM

Date :- .....

Inspector :- A.E. RWD WORKS SUB DIVISION, PIRO

Period- 11.08.2021 to 10.11.2021

Unit OF Required in each Kilometer

No	standard Of Work Item	Work	Unit	1	2	3	4	5	6	7	8	9	10	Comments
OM100	<b>Sealed payment</b>													
OM101	Pothole Patching		m <sup>2</sup>	NIL	NIL									No pothole found
OM102	Surface Depression and Rut patching		m <sup>3</sup>	NIL	NIL									No Surface Depression and Rut patching found
OM103	Crack Sealing		Lm	NIL	NIL									No crack
	Surface Treatment			NIL	NIL									Not required
OM104	(a) Loss of Aggregate (Surface Ravelling)		m <sup>2</sup>	NIL	NIL									No Loss of Aggregate ( Surface ravelling ) found
	(b) Bleeding / Flushing		m <sup>2</sup>	NIL	NIL									No bleeding / furnishing found
	© Crocodile Cracking		m <sup>2</sup>	NIL	NIL									No Crocodile cracking found
OM105	Edge Repair		m <sup>2</sup>	NIL	NIL									Notified & repaired
OM106	Digouts		m <sup>2</sup>	N.A.	N.A.									
OM107	Concrete pavement		m <sup>3</sup>	N.A.	N.A.									
	Other activities													
OM200	<b>Shoulder</b>													
	Unsealed Shoulder													
OM201	(a) Edge Drop-off		Lm	NIL	NIL									No Edge Drop off found
	(b) Roughness, Scouring or Potholes		Lm	NIL	NIL									No Roughness, Scouring or Potholes found
	(c) Holding water		Lm	NIL	NIL									No Holding Water Found
OM202	Embankment Repair		M <sup>3</sup>	NIL	NIL									Notified & repaired
	Other activities (Rain Cuts)			N.A.	N.A.									
OM300	<b>Drainage including culverts major</b>													
OM301	Surface Drains & Verge		Lm	N.A.	N.A.									NA
OM302	Culvert Cleaning		No	NIL	NIL									DONE
OM303	Culvert and pit Repair		M <sup>3</sup>	NIL	NIL									DONE
	Other activities(Whilw washing)		M <sup>2</sup>	NIL	NIL									Not required
OM400	Vegetation													
	Grass Control													Need More Cleaning
OM401	(a) Roadside- General Tidy		Ha	NIL	NIL									Done
	(b) Clear near Safety signs, kilometer posts and roadside furniture		Ha	NIL	NIL									Done
OM402	Tree and Shrub Management		No	NIL	NIL									Done
	Cutting Of Branches Of Trees		No	NIL	NIL									Done
	Cutting Of Shrubs From Road Way		No	NIL	NIL									Done
	Other activities (Trimming of Grass)		M <sup>2</sup>	NIL	NIL									Done
OM500	<b>Safety Signage and Road</b>													Not Required
OM501	Signs Maintenance		No	NIL	NIL									Not Required
OM502	Guard Stones		Lm	NA	NA									N.A.
OM503	Distance Stones		No	NA	NA									N.A.
OM504	Road Marking		M <sup>2</sup>	NIL	NIL									Not Required
	<b>Other activities</b>													

 J.E. RWD WORKS  
 Section, Piro

 A.E. RWD WORKS  
 SUB DIVISION, Piro

 Executive Engineer  
 Rural works Department  
 Works Division, Piro