

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, पटना

पत्रांक :- 2077

पटना / दिनांक :- 09/11/23

प्रेषक,

ई0 राजेश कुमार चौधरी,
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, पटना ।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बी.आर.आर.डी.ए. ,
ग्रामीण कार्य विभाग,
बिहार, पटना ।

विषय :- शीर्ष-3054 (एम.आर.), बिहार ग्रामीण पथ अनुरक्षण नीति 2018 योजना अन्तर्गत
वित्तीय वर्ष 2023-24 के अन्तर्गत आवंटन का अधियाचना के संबंध में ।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष-3054 (एम.आर.), बिहार ग्रामीण
पथ अनुरक्षण नीति 2018 योजना अन्तर्गत वित्तीय वर्ष 2023-24 के अन्तर्गत आवंटन का
अधियाचना का मांग पथ वार कर आवश्यक कार्रवाई हेतु संलग्न किया जाता है ।

अतः आपसे अनुरोध है कि उक्त योजना अन्तर्गत आवंटन उपलब्ध कराने की
कृपा की जाय ताकि संवेदक का भुगतान किया जा सके ।

अनु०:- यथोक्त ।

विश्वासभाजन

09/11/23

(ई0 राजेश कुमार चौधरी),
कार्यपालक अभियंता

ग्रामीण कार्य विभाग, कार्य प्रमंडल, पटना

09/11/23

09/11/23

Form GFR 19-A

(See Government of India's Decision (I) below Rule - 150)

Form of Utilization Certificate 16.10.2023

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs) By Bank	Amount Received (in lacs)	Particulars
1	3054 (MR) New Maintenance Policy, 2018	Letter No. 140 Dated 16.10.2023	8478.07703	Certified that out of Rs. 8478.07703 lacs of grants in aid sanctioned during upto 16.10.2023 in favour of Executive Engineer, RWD Works Division, Patna under this Department, a sum of Rs. 8388.50738 lacs has been utilized for the purpose of 3054 (MR) as given in the margin for which it was sanctioned and that the balance of Rs. 89.56965 remaining unutilized at the end of the period under report.
		Total	8478.07703	

Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / and being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which.

Kinds of Checks exercised :-

- Works have been supervised by Executive Engineer / Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer / Superintending Engineer.
- Construction material have been tested,
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works.

G.K. 17/10/23

Executive Engineer
RWD Works Division, Patna
17/10/23

Scanned with OKEN Scanner

Scanned with OKEN Scanner

Scanned with OKEN Scanner

Scanned with OKEN Scanner

Scanned with CamScanner

Requisition Format for Scheme Head-(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Division :- Patna

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA) Length (in Km)	Amount of (in Lakh)	Initial Rectification on Surface (in Lakh)	5 Year Routine Maintenance (in Lakh)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of Road (in mm/Km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RMP/PA/PA/723/00011	Gram Kandaap me Pradhan mantri gram sadak se kandaap pakatkar vilambhar rola tak swami vivekanand singh (Viveka babu) ke Ghar tak	10100104005	1942/29 03 2023	0.550	41.656	30.0942	3.5818	33/MOD/23/24/19 08 2023	18.05.2024	-	2709.5	25mm SDBC	5%	-	-	30.78420	work is not completed to 100% as per the scheme approved by the authority. The work is in progress.
2	RMP/PA/PA/723/00000	Raksha Bandh-Lanka Kachaura Mahalalit Tola	10100102252	1447/28 02 2023	1.820	150.512	106.28279	16.35545	27/MOD/23/24/19 07 2023	10.04.2024	-	2802.4	25mm SDBC	5%	-	-	106.19279	work is not completed to 100% as per the scheme approved by the authority. The work is in progress.
3	RMP/PA/PA/723/00011	Sampachak me chipura panchayat ke gram chipura kala (baki chipura) pakchim transform se dakshin ravida tola hote hue purab quarter mandir tak paki sadak nirman	10100104078	1942/29 03 2023	1.000	66.552	46.73931	9.426	33/MOD/23/24/19 08 2023	18.05.2024	-	2820.3	25mm SDBC	5%	-	-	46.72531	work is not completed to 100% as per the scheme approved by the authority. The work is in progress.
4	RMP/PA/PA/723/00000	Sampachak Prachand ke Chipura Khurd Gram se Dasechin Diwanendar singh ke ghar se Chipura kala Mahalalit Tola hote hue purab kandi kachia (Chipura Khushkhatk man sadak baki	10100104064	447/28 02 2023	1.200	140.615	106.25569	10.2023	27/MOD/23/24/19 07 2023	10.04.2024	-	2795.167	25mm SDBC	5%	-	-	106.15590	work is not completed to 100% as per the scheme approved by the authority. The work is in progress.
Total																289.85820		

Divisional Account Officer
R.W.D. Works Division, Patna

Executive Engineer
RWD Works Division, Patna

Name of the Road : Sampatchak Prakhand ke Chipura Khurd Gram
se Dacchin Dharmendar singh ke ghar se Chipura kala Mahadalit
Tola hote hue purab kandhi kandha(Chipura-Khushhaalchak main
sadak) tak

Length : 1.2

Package No. :RM/PA/PAT/23/0006

Division : Patna

Block : Sampatchak

Contractor Name : Dhaneshwar Nath Constructions

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event			
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD						
09/11/23	10:28:08	98	0.1	260	0	2600	2650	G	25.531631	85.153468	Normal	$Y = 0 * X^2 + 0.936 * X + 278.4$		
09/11/23	10:28:46	98	0.1	270	30.3	2700	2720	G	25.531715	85.15162	Normal	X = 3300		
09/11/23	10:29:05	98	0.1	280	30.2	2800	2892	G	25.531903	85.150489	Normal	Y = 3367		
09/11/23	10:29:35	98	0.1	260	30.3	2600	2635	G	25.531954	85.149881	Normal			
09/11/23	10:29:58	98	0.1	270	20.1	2700	2792	G	25.532959	85.149807	Normal	(R)RURAL ROAD		
09/11/23	10:30:25	98	0.1	290	30.3	2900	2960	G	25.534119	85.149474	Curve	Good	Average	Poor
09/11/23	10:30:58	98	0.1	270	30.3	2700	2735	G	25.534217	85.148619	Normal	<4000	4001-5000	>5001
09/11/23	10:31:22	98	0.1	290	20.2	2900	2992	G	25.535118	85.148192	Curve			
09/11/23	10:32:51	98	0.1	260	30.3	2600	2647	G	25.531498	85.149821	Normal			
09/11/23	10:33:37	98	0.1	270	30.3	2700	2748	G	25.530248	85.14979	Normal			
09/11/23	10:34:15	98	0.1	290	30.3	2900	2941	G	25.529184	85.149815	Normal			
09/11/23	10:34:58	98	0.1	280	20.2	2800	2830	G	25.531379	85.148779	Normal			
Total			1.2	3290	302.8	32900	33542		306.385925	1021.79976				
Average						2741.667	2795.167							

Supervisor
09/11/23

09/11/23

Analyzer

Name of Customer : Dhaneshwar Nath Construction
 Name of Work/ Road : Sampatchak Prakhand ke chip
 Lab Job number :
 Date : 09-11-2023
 Section No. : 98

Test Date : 09-11-2023 Road Name : Sampatchak Prakhand ke chip
 Machine No : 374 Road Type : (R) RURAL ROAD
 Start S No : Side : Interval
 Start E No :
 Weather : UV Range : 1635 To 4000 1000 mm/km
 Start Location : Dist Range : 0 To 1.3 0.1 * 1000 m
 End Location : Equation : $Y = 0 * X^2 + 0.936 * X + 278.4$

Print

Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\eerwdpat\Desktop\Dhaneshwar nath construction\steco.xlsx Section No. : 98, Eqn : $Y = 0 * X^2 +$
 Name of Customer : Dhaneshwar Nath Construction, Name of Work/ Road : Sampatchak Prakhand ke chipura khurd

UV
mm/
km

1635

0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8 0.9 1 1.1 1.2

Distance * 1000 m

Supriya
09/11/23

09/11/23