

MMGSY-WB-20-Sherghati-02

Toi to Sihu Kabristan

(Kabristan Se

Makou Kinche Hote Maadrasa fak)-2:602 Km

Shedule XLV Form No. 134.

Ag.No- 29 SBDI- 2021-2022

SHERGHATI

DIVISION

SHERGHATI

SUB-DIVISION

Ajay Kumar

Measurement Book

1303

1st Year Maintenance bid

54

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -	Grading of Road from				
	To, To Sikkuli Kabinah				
Agency -	A Jay Kumar				
Agreement No -	29 SDD/2021-22				
Work start date -	29/09/21				
Date of completion -	28/09/22				
Item (1)	Destruction of Ram				
	culls				
	10	5.10	1.10	0.30	= 16.83 M ³
	8	4.20	0.95	0.25	= 7.98 M ³
	7	4.95	1.20	0.20	= 8.31 M ³
	8	3.85	1.25	0.30	= 11.55 M ³
	10	2.40	1.15	0.30	= 8.28 M ³
	15	4.40	1.20	0.25	= 19.8 M ³
	16	6.10	1.10	0.30	= 32.20 M ³
	8	3.90	1.20	0.30	= 11.23 M ³
					116.18 M ³
Item (2)	Making up Berms				
	and shoulder				
	15	5.40	1.10		= 89.10
	10	3.10	0.90		= 27.90
	12	4.70	1.15		= 64.86
	15	1.20	0.95		= 17.10
	13	4.90	1.25		= 79.62
	15	6.20	1.10		= 102.3

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item (10) Maintenance of Road sign					
		2.6	10m		
Item (11) Maintenance of 20m and 10m sign					
		2.6	10m		
Item (12) Cutting of branches of Tree - 7 No					
Item (13) Cutting of shrubs for roadways					
		2300	10m		
Item (14) Trimming of grass and weeds					
2x 10x 30x 1.10 =					660 m ²
1x 10x 30x 1.00 =					300 m ²
2x 9x 30x 1.20 =					648 m ²
2x 8x 30x 1.25 =					600 m ²
1x 3x 30x 1.00 =					90 m ²
					2298 m ²
Item (15) White washing of C.D. wall					
8x4x 6.20x 0.140 =					59.52
6x2x 6.20x 0.30 =					22.32
					40.92
					81.84 m ²

Continuation

A. L. Arora
23/06/23
DE

ABSTRACT OF COST

58

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/15-1 CA) Restoration of Raincuts					
V.T.M.B.P.H. - (54)					
item no (1) - 116.18 M					
as 407.70/M ² -					473672
(2/15-2 C) Making up of Bores/					
Shoulder					
V.T.M.B.P.H. - (54)					
item (2) - 645 M ²					
as 60.58/M ² -					390742
(3/15-3 D) Repair of Path holes					
V.T.M.B.P.H. - (55)					
item (3) - 0.15 M					
as 9177.92/M ² -					137720
(4/15-3 (ii)) Patch repair over					
Path holes					
V.T.M.B.P.H. - (55)					
item (4) - 53.85 M ²					
as 239.34/M ² -					129120
(5/15-3 (ii)) Patch repair over					
Bituminous surf @					
V.T.M.B.P.H. - (55)					
item (5) - 53.38 M ²					
as 255.61/M ² -					136440
(6/10-6) Crack sealing of					
joint of roads					
V.T.M.B.P.H. - (56)					

Continuation

60
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(12/15-12ii)	cutting of branches of 7000				
	V.T.M.B.P.H. - (57)				
	item (12) - 2nd				
	or 119.97/d				840 ^{sq}
(13/15-12ii)	cutting of shrubs from road way				
	V.T.M.B.P.H. - (57)				
	item (13) - 2300 N				
	or 2.10/H				16330 ^{sq}
(14/15-12iii)	Trimming of grass and weeds				
	V.T.M.B.P.H. - (57)				
	item (14) - 2288 m ²				
	or 2.37/m ²				5446 ^{sq}
(15/15B)	white washing of parapet				
	V.T.M.B.P.H. - (57)				
	item (15) - 81.84 m ²				
	or 17.01/m ²				1392 ^{sq}
					1,69,332 ^{sq}
	Loss 5-72% below				9686 ^{sq}
					1,59,646 ^{sq}

A. Kumar
23/06/23
n

Continuation