

कार्यपालक अभियंता का कार्यालय  
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक-2499...../बक्सर

दिनांक-08/11/23

प्रेषक,

कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव  
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)  
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन

08/11/23

कार्यपालक अभियंता  
ग्रा०का०वि०, कार्य प्रमंडल- बक्सर

08/11/23

**FORM GFR 19-A**  
(SEE Government of India's Decision (I) below Rule-150)  
Form of Utilisation Certificate upto the month of Oct 2023

**MR (3054) New Maintenance Policy 2018**

**IU - RWD (W), Div.- Buxar**

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 147, dt.-01/11/2023	102.583536	Certified that out of Rs. 102.583536 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 10118.17635 lacs has been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 11.31270 lacs remaining unutilized at the end of the period under.
<b>Total -</b>				

- 2 Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

**Kind of Checks exercised :-**


- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

- 3 **Physical Progress achieved :-**

- Construction of Road works
- Construction of CD works

  
Executive Engineer

R.W.D. (w) Div. Buxar

  
08/11/23

Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

2 of Works Division- RWD, Works Division- Buxar


Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (In Lakh)	up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (in Km)	Amount (In Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
5	RM/BU/BU X/23/0001	L046-L028 To Lal Singh ke Dera	10401902082	1796 dt20.03.2023	1.1	51.78	35.77449	32.51599	05/MBD/2023-24 dt 20.06.2023	03-04-2023	2190	25 mm	5.01%	33.40669	33.40669	2.32887	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer  
RWD (W), Div.- Buxar

28/7/23  
RK  
8/11/23

File : H:\shailesh\19101251 (1).Xls, Section No. : 35, Eqn :  $Y = 0 \cdot X^2 + 0.816 \cdot X + 249$   
 Name of Customer : Shailesh Singh, Name of Work/ Road : L046-L028 Lal Singh Ke Dera, Lab Job number :



19.10.23  
 J.E

19.10.23

# Road Name:- L046-L028 to Lal Singh ke Dera Contractor Name:-Shailesh Singh

Date	Time	Section	Length	Bumps	Speed	OR	IRI/TEGORY	Latitude	ongitude	Event
19/10/23	8:32:30	No.	in km	in mm	Rate	mm/km	mm/km			
19/10/23	8:33:5	35	0.1	240	10.1	2400	2207 G	25.70171	84.16689	Normal
19/10/23	8:33:5	35	0.1	210	10.1	2100	1962 G	25.70168	84.1679	Speed Brea
19/10/23	8:33:40	35	0.1	230	10.1	2300	2125 G	25.70145	84.16887	Normal
19/10/23	8:34:0	35	0.1	210	10.1	2100	1962 G	25.70127	84.16985	Normal
19/10/23	8:34:51	35	0.1	270	10.1	2700	2452 G	25.70102	84.17084	Normal
19/10/23	8:35:0	35	0.1	220	10.1	2200	2044 G	25.70084	84.1718	Normal
19/10/23	8:35:26	35	0.1	240	10.1	2400	2207 G	25.70069	84.17281	Normal
19/10/23	8:36:1	35	0.1	230	10.1	2300	2125 G	25.70054	84.1738	Normal
19/10/23	8:36:1	35	0.1	290	10.1	2900	2615 G	25.70036	84.17481	Normal
19/10/23	8:37:12	35	0.1	240	10.1	2400	2207 G	25.70012	84.17579	Normal

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2400$$

$$Y = 2207$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

IRI Value=2190

Machine ID=415

19.10.23  
J.E


19.10.23

**कार्यपालक अभियंता का कार्यालय**  
**ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर**


का0आ0स..... बक्सर/ दिनांक.....

**कार्यालय आदेश**

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L046-L028 TO LAL SINGH KE DERA पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।

  
19.10.23

कनीय अभियंता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रशाखा सिमरी

  
19.10.23

कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल, बक्सर