

Name of Customer : SAM ROAD - TO KUSHDEHRA
 Name of Work : Shree Associates Private Limited
 Road :
 Lab Job number : 55
 Date : 02-06-2009
 Section No. : 55


Test Date :	28-04-2010	Road Name :	SAM ROAD - TO KUSHDEHRA
Machine No :	412	Road Type :	(A) ASPHALTIC
Start S No :	347	Side :	Right
Start E No :	362	Interval :	
Weather :	Normal	UIV Range :	1015 To 4000 mm/km
Start Location :	6656.84 0975;	Dist Range :	0 To 16 0.1 * 1000 m
End Location :	6874.84 0987;	Equation :	0 * X^2 + 1.000 * X + 415.2

Print Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\BHRDAS\Desktop\2023\Bump Report\Sushma SASARAM ROAD - TO KUSHDEHRA\DATA\UI -
 Name of Customer : SASARAM ROAD - TO KUSHDEHRA Name of Work/Road : Sushma Associates Private Limited.



Prof
 22/06/23
 7E

MUMMA
 22.06.23
 EE

Good Name-SASARAM ROAD - TO KUSHDEHRA

Contractor Name- Sushma Associates Private Limited

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGO ROAD	Latitude	Longitude	Event
22/6/23	16:39:16	95	0.1	180	10.1	1800	2215	G	24.86656	84.09757	Normal
22/6/23	16:40:0	95	0.1	250	10.1	2500	2915	G	24.86783	84.09830	Normal
22/6/23	16:40:0	95	0.1	260	20.2	2600	3015	G	24.86784	84.09832	Normal
22/6/23	16:40:27	95	0.1	190	20.2	1900	2315	G	24.86838	84.09859	Normal
22/6/23	16:40:46	95	0.1	240	20.2	2400	2815	G	24.86927	84.09912	Normal
22/6/23	16:41:2	95	0.1	180	10.1	1800	2215	G	24.86997	84.09947	Normal
22/6/23	16:41:30	95	0.1	250	10.1	2500	2915	G	24.86997	84.09947	Normal
22/6/23	16:41:37	95	0.1	260	20.2	2600	3015	G	24.87045	84.09994	Normal
22/6/23	16:42:0	95	0.1	200	20.2	2000	2415	G	24.87083	84.10019	Normal
22/6/23	16:42:12	95	0.1	240	30.3	2400	2815	G	24.87129	84.10057	Normal
22/6/23	16:42:24	95	0.1	200	30.3	2000	2415	G	24.87217	84.10132	Normal
22/6/23	16:42:48	95	0.1	250	30.3	2500	2915	G	24.87205	84.10193	Normal
22/6/23	16:42:55	95	0.1	270	30.3	2700	3115	G	24.87196	84.10213	Normal
22/6/23	16:43:12	95	0.1	160	20.2	1600	2015	G	24.87159	84.10360	Normal
22/6/23	16:43:25	95	0.1	280	20.2	2800	3215	G	24.86874	84.09876	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor

IRI Value

Average IRI-2688

22/6/23
22/6/23
7E

22.06.23
7E

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

पत्रांक.....1537
प्रेषक,

डिहरी/दिनांक...24.11.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी –सह-सचिव,
ब्रांडा,
भूमि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :- **MR New Maintenance policy-2018** में किये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि **MR New Maintenance policy-2018** अर्न्तगत कराये गये कार्य के विरुद्ध संवेदक को भुगतान करने हेतु अध्याचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सभी डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासभाजन

NKumar
24.11.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

Itin
24-11-23

FORM GFR 19 -A

(SEE GOVERNMENT of India's Deceslon (I) below Rule - 150)

Form of Utilisation Certificate upto the Month of November. 2023

NEW MAINTENANCE POLICY 2018 MR (3054)

PIU - RWD DEHRI

S.No	Name of Scheme	Sanction No. & Date	Amount Received	Particulars
		With amount(in Rs. Lacs)	(In Rs. Lacs)	
1	Contruction of Rural Road Under MR-3054	152 16/11/2023	5179.77692	Certificate that out of Rs. 4907.96192 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 4804.22516 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 375.55176 Lacs remaining unutilized at the end of the period under.
TOTAL			4907.96192	

Certified that I have satisfied myself that the conditions on which the grand-in-aid


- 2 was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer / Supertending Engineer.
- Periodical inspectioin has been conducted by Executive Engineer / Supertending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.


3 Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works.



D.A.O

RWD (W) Div. Dehri



Executive Engineer

RWD (W) Div. Dehri


24-11-23

Office of the Executive Engineer, Rural Works Department, Works Division, Dehri
Requisition formate Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

Sl No.	Package No.	Name of Road	Project Id as per MIS	Administrative Approval (AA) Letter No and Date	Administrative Approval (AA)		Agreement (in Lakh)		Agreement No and Date	Date of Completion as per Agreement	Actual Date of Completion	Value of Bt (in mm/KM)	Thickness of Bitumin Layer (in mm)	Value of Bitumin Content in Percentage	Previous total amount (in Lakh)	Up to Date expenditure as per MIS (in Lakh)	Requisition Done (in Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/RO/DEH/22/0015	PWD Path to Rampur Farm Via Kerpa Village	10301206017	1413/08.09.2022	1.600	108.966	60.98.	18.70604	MR/DEHRI/15 MR(3054)/MBD /2022-23/06.03.2023	05.12.23	28.08.23	2697	25 MM	5%	55.880	55.880	1.77483	Complete
2	RM/RO/DEH/22/0015	SASARAM ROAD - TO KUSHDEHRA	10301102092	1413/08.09.2022	1.510	112.138	69.44911	13.84084	MR/DEHRI/15 MR(3054)/MBD /2022-23/06.03.2023	05.12.23	25.08.23	2688	25 MM	5%	55.5592	55.5592	13.40611	Complete
3	RM/RO/DEH/22/0015	DABAUT - BAULTYA ROAD	10301102023	1413/08.09.2022	2.551	168.156	98.91719	21.37243	RWD/DEHRI/15 MR(3054)/MBD /2022-23/06.03.2023	05.12.23	26.08.23	2607	25 MM	5%	84.07961	84.07961	14.51691	Complete

नोट:-

विभागीय फॉर्म-मु030(मु) 3054-4-04/2020 पार्ट 4 5047 दिनांक 23.12.2021 के आलोक में प्रमाणित किया जाता है कि-

- गुणवत्ता पूर्ण एवं विविधियों के अनुरूप कार्य कराने के बाद MB में दर्ज किया गया है।
- सम्बंधित कार्य कर्मीय अभियंता द्वारा कराया गया (100% जांचा गया) सहायक अभियंता द्वारा 50% तथा कार्यपालक अभियंता द्वारा 10% जांचा गया तथा MIS पर Upload किया गया।

D.A.O
RWD (W) Div. Dehri

EXECUTIVE ENGINEER
RWD, WORKS DIVISION, DEHRI

24-11-23