

Particulars	Details of actual measurement				Contents of area
	No.	L	E	D	
Adjustment of cost					
cost on Air Bill					
(Ad B/W 1/4 m/s)					

(1) Restoration of Rampart

Barren - do do					
P-58 Item no-1					
2126 m ² @ 294.95/m ² =					5377 =

(2) Making up of Barren

Shoulder - Shallow (access to)					
P-57 Item No-2					
10052 m ² @ 47.24/m ² =					4768 =

(3) Repair of pot holes

With 75 mm Gm do do					
P-59 Item no-3					
1-58 m ² @ 1253.24/m ² =					19803 =

(4) Patch repair over pot holes

With 20 mm Gm do do					
P-60 Item No-4					
2102 m ² @ 335.40/m ² =					7074 =




(5) Patch repair on

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Plumwood 645 ft 20 mm th					
P-60 stem No-5					
21.09 m ² @ 357.54 m ² =					7541 =
(6/7) Maintenance of H. pipe					
Culverts do-do					
P-61 stem No-6					
1 Nos @ 843.32 m ² =					843 =
(7/8) maintenance of Slab					
Culverts do-do					
P-61 stem No-7					
1 Nos @ 1774.98 m ² =					1775 =
(8/9) Maintenance of Road sign do-do					
P-61 stem No-8					
0.15 km @ 851.75 km ² =					128 =
(9/10) Maintenance of 200m and Kilometer stone do-do					
P-61 stem No-9					
0.18 km @ 502.27 km ² =					90 =
(10/11) Cutting of branches of tree from roadway					

Continuation

60 = 48399 =

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
P-61	Stem No	10			
8 Nos @ 72.77 / ear					73 =
12) White wash of parapet wall and free do do					
all Complete job					
P-61	stem no-	11			
38.47 m ² @ 12-30 / m ²					473
					489450
less 8.79 % for Agreement					43020
					446430
    19/11/2018 21/11/2018 28/10/2018					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
Yearly maintenance Bill					
(A.U. City Mado T.M.B.)					

(1/1) Restoration of Rain
cut/Berms with soil
P-75 Item-1
27.12 m³ @ 299.93/m³ = 8134.00

(1/2) Making of Berms/
Shoulder stripping of
excess soil
P-75 Item-2

151.67 m² @ 47.29/m² = 7172.00

(3/3) Repair of pot hole
with 75 mm BM do-
do - all complete job

P-76 Item No. 3

~~2.72 m³~~

2.64 m³ @ 12533.34/m³

= 33088.00

(1/4) Patch repair over
pot hole with 20
mm primix do-do-
all complete job

Particulars	Details of actual measurement				Centimetre of area
	No.	L.	B.	D.	
P-77 item-4					
34.78 m ² @ 335.40/m ²					
(S/S) patch repair over bituminous surface with 20 mm per inch carpet with seal coat etc - do.					
P-77 item-5					
34.48 m ² @ 357.54/m ²					

(S/S) maintenance of pipe culverts do - do - all complete job					
P-77 item-6					
1 nos @ 848.37/m ² = 848.37					

(7/1) maintenance of slab culvert do - do - all complete job					
P-77 item-7					
1 nos @ 1778.98/m ² = 1778.98					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8/9) Maintenance of Road					
Sign do - do all					
Complete job					$\approx 0.15 \text{ km}$
P-78 item-8					
$0.15 \text{ km} @ 851.75/\text{km} = 852 = \omega$					
(9/9) Maintenance of road					
m and km Stone					
do - do - all complete					
job					
P-78 item-9					
$0.24 \text{ km} @ 502.27/\text{km} = 502 = \omega$					
(10/10) Cutting of					
branches of tree					
from roadway do -					
do - all complete					
P-78 item-10					
$\pm 1405 @ 72.77/\text{Nos} = 73 = \omega$					
(11/11) while washing					
parpet wall and tree					
P-78 - item 10-11					
$38.47 \text{ m}^2 @ 12.30/\text{m}^2 = 7173 = \omega$					
Continuation					
$C.O. = 76951 = \omega$					

Continuation