

2nd year Maintenance

40

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work:-	PS Tibudihuli to				
	Malak Tola				
Agency:-	Zeva construction and deve				
	in Pvt. Ltd.				
Agreement No.:-	59 SDD of 2020-21				
Date of Work order:-	01.02.2021				
Date of completion					
as per agreement:-	31.1.22				
Date of completion actual:-	15.6.21				
Date of entry:-	12.8.23				
1/1 Restoration of rain cuts					
with Soil					
2x4 x 30.0 x 1.0 x 0.30m-					72.0 sq

	limited to	67.25 m ²
2/2	Makeup up of bumpy and shoulder	
	2x7x30.0 x 1.0 m	- 420.0 m ²
	limited to	374.63 m ²
3/5	Patch repair on already filled pot hole	
	8 x 2.20 x 1.25 m	- 30.80 m ²
	8 x 1.85 x 1.55 m	- 22.94 m ²
		53.74 m ²
	limited to	52.03 m ²
4/7	Maintenance of home pipe culverts	3 m ²
5/1	Maintenance of	

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
L.C. C/14					R 283=10
					R 78097=81
Can C/15-1.09 for agreement (4)					R 976=22
					R 77121=53
ADD for rounding (4)					0541
					R 77122=09
C/8	17.8.23				17.8.23
					17.8.23
					SE/5/17/75
calculations for S.F. and Royalty					
S.F.					
C/W = 123.62 m ²					
@ 34=71 Pn R 4291=0					10% - 429=10
Stone chips - 1.72 m ³					
C R 7000 Pn R 1204=0					10% - 120=40
					R 550=00
Royalty					
C/W = 123.62 R 332=0 Pn					- 4079=41
Stone chips - 1.72 m ³ R 150=0 Pn					- 254=00
					R 4337=00
					17.8.23
					SE/5/17/75

Continuation