

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल खड़गपुर-तारापुर

गो0-8986915054

ई गेल - ee.kh.tarapur.rwd2@gmail.com

पत्रांक - 11/10/23 / तारापुर
प्रेषक,

दिनांक 11/10/2023

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, खड़गपुर-तारापुर।

सेवा में,

नोडल पदाधिकारी,
"नई अनुरक्षण नीति 2018" (3054-MR)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय :- शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत Bambar to Champa Chak Village Road Phase-II पथ के निर्माण में संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में।


महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत Bambar to Champa Chak Village Road Phase-II पथ कार्य पूर्ण हो चुका है। इस कार्य के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में भर कर की जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0:-यथोक्त।

विश्वासभाजन


11/10/23

कार्यपालक अभियंता
ग्रामीण कार्य विभाग

कार्य प्रमंडल खड़गपुर-तारापुर
11/10/23

Office Of The Executive Engineer
Rural Works Department
Works Division, Kharagpur-Tarapur

Requisition Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Sl. No.	Package No./ Batch No.	Name of Road	Project ID as per MIS	Administrative Approval(AA) Letter No. & Date	Administrative		Agreement Amount		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumen Layer in mm	Value of Bitumen content in Percentage	Previous Total Alloted Amount (in Lakh)	Up-to-date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	RN/MU/KHA/ 23/0003	Bambar to Champa Chak Village Road Phase-II	20803702095	463 04.07.2022	3.000	201.47900	137.15457	27.12381	29MIBD/2022-23 05.01.2023	04.10.2023	15.03.2023	2682	SDBC-25mm	SDBC-5.0	0.00000	0.00000	137.15457	Complete

[Signature]
11/10/2023
Divisional Account Officer
Rural Works Department
Works Division Kharagpur-Tarapur

[Signature]
11/10/23
Executive Engineer
Rural Works Department
Work(s) Division Kharagpur-Tarapur

EXECUTIVE ENGINEER, WORK DEPARTMENT, WORKS DIVISION, KHARAGPUR-TARAPUR, (MUNGER)**FORM GFR19 A**

(See Government Of India's Decesion (1) Below Rule 150)

(Form Of Utilization Certificate up To The Month Of Up To October .2023)

(MR New Maintenance Policy 2018)

No.	Name Of Scheme/Purpose	Sanctioned with Date	Sanctioned Amounts(In Lacs-Rs.)	Amount Recived(IN Rs. Lacs)	Particulars
1	Construction of Rural Road & Bridge underMR New Maintenance Policy 2018	Ltr. No. 35 Dt. 13.10.2022 Ltr. No.47 dt 24.11.2022 Ltr. No.04 dt 10.01.2023 Ltr. No.10 dt 27.01.2023 Ltr. No.21 dt 20.02.2023 Ltr. No.33 dt 07.03.2023 Ltr. No.56 dt 28.03.2023 Ltr.No.78 dt 24.05.2023 Ltr.No.85 dt 14.06.2023 Ltr.No.92 dt 28.06.2023 Ltr.No.100 dt 14.07.2023 Ltr.No.106 dt 02.08.2023	9543.24156	9543.24156	Certified that out of Rs. 9543.24156 Lakh received up to date in Favour of Executive Engineer, RWD, Kharagpur-Tarapur Sum of Rs.8876.20949 Lakh has been Utilized for the Purpose of MR New Maintenance Policy 2018 Program Fund Scheme as given In the margin for Which it was sanctioned and that the balance of Rs. 667.03207 Lakh remaining Untlilzed amount at the end of the period Under.

- 2 Certyified that I have satisfied myself that the condition on which the grants in aid was sanctioned have been duly fulfilled /are being fulfilled And that I have exercised the checks to see that the money was actually utilized for which it was sanctioned.


11/10/2023
Divisional Account Officer
Rural Works Department
Works Division Kharagpur-Tarapur


11/10/23
Executive Engineer
R.W.D. (W) Div, Kharagpur-Tarapur
(Munger)

Name of work : Bambar to Champa Chak Village Road Phase-II

Name of customer : Kartik Prasad

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	U/(mm/Km)	Corrected U/(mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
14/09/23	16:56:42	108	100	100	26.0 cm	4.4 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.0718603	N	86.5637064	E	Normal
14/09/23	16:56:59	108	100	200	23.0 cm	20.6 Km/Hr	2300.0 mm/Km	2454	3.37	Good	25.0725069	N	86.5632029	E	Normal
14/09/23	16:57:14	108	100	300	25.0 cm	23.4 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.0725603	N	86.5627451	E	Normal
14/09/23	16:57:22	108	100	400	13.0 cm	39.5 Km/Hr	1300.0 mm/Km	1485	2.15	Good	25.0725603	N	86.5627451	E	Normal
14/09/23	16:57:49	108	100	500	20.0 cm	15.6 Km/Hr	2000.0 mm/Km	2163	3.01	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	16:57:54	108	100	600	11.0 cm	41.4 Km/Hr	1100.0 mm/Km	1291	1.9	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	16:58:00	108	100	700	26.0 cm	75.5 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	16:58:10	108	100	800	23.0 cm	38.1 Km/Hr	2300.0 mm/Km	2454	3.37	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	16:58:29	108	100	900	31.0 cm	18.3 Km/Hr	3100.0 mm/Km	3229	4.3	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	16:58:54	108	100	1000	30.0 cm	12.3 Km/Hr	3000.2 mm/Km	3132	4.19	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	16:58:57	108	100	1100	24.0 cm	132.3 Km/Hr	2400.0 mm/Km	2550	3.49	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	16:58:39	108	100	1200	27.0 cm	8.8 Km/Hr	2700.0 mm/Km	2841	3.84	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	17:00:10	108	100	1300	29.0 cm	11.1 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	17:00:13	108	100	1400	26.0 cm	48.5 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	17:00:26	108	100	1500	14.0 cm	45.5 Km/Hr	1400.0 mm/Km	1582	2.27	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	17:00:41	108	100	1600	33.0 cm	22.5 Km/Hr	3300.0 mm/Km	3423	4.53	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	17:01:00	108	100	1700	30.0 cm	19.8 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.0735922	N	86.5610666	E	Normal
14/09/23	17:01:24	108	100	1800	28.0 cm	15.0 Km/Hr	2800.0 mm/Km	2938	3.95	Good	25.0785894	N	86.5564280	E	Normal
14/09/23	17:01:38	108	100	1900	29.0 cm	23.4 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.0790987	N	86.5554895	E	Normal
14/09/23	17:02:17	108	100	2000	27.0 cm	23.4 Km/Hr	2700.0 mm/Km	2841	3.84	Good	25.0796957	N	86.5547571	E	Normal
14/09/23	17:02:30	108	100	2100	29.0 cm	2.4 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.0806723	N	86.5524225	E	Normal

11.10.23
GR

Name of work : Bambar to Champa Chak Village Road Phase-II

Name of customer : Kartik Prasad

(R) Rural Road


Good	Average	Poor
< 4000	4001 - 5000	> 5000

14/09/23	17:02:53	108	100	2200	31.0 cm	21.3 Km/Hr	3100.0 mm/Km	3229	4.3	Good	25.0806570	N	86.5514994	E	Normal
14/09/23	17:03:10	108	100	2300	25.0 cm	21.0 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.0803651	N	86.5536641	E	Normal
14/09/23	17:03:40	108	100	2400	27.0 cm	23.4 Km/Hr	2700.0 mm/Km	2841	3.84	Good	25.0805301	N	86.5526101	E	Normal
14/09/23	17:04:05	108	100	2500	23.0 cm	27.5 Km/Hr	2300.0 mm/Km	2454	3.37	Good	25.0812210	N	86.5511101	E	Normal
14/09/23	17:04:35	108	100	2600	25.0 cm	29.5 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.0819331	N	86.5508710	E	Normal
14/09/23	17:04:58	108	100	2700	28.0 cm	20.1 Km/Hr	2800.0 mm/Km	2938	3.95	Good	25.0818101	N	86.5493701	E	Normal
14/09/23	17:05:25	108	100	2800	24.0 cm	21.0 Km/Hr	2400.0 mm/Km	2550	3.49	Good	25.0823801	N	86.5483801	E	Normal
14/09/23	17:05:53	108	100	2900	26.0 cm	15.6 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.0825801	N	86.5487341	E	Normal
14/09/23	17:06:10	108	100	3000	28.0 cm	8.9 Km/Hr	2800.0 mm/Km	2938	3.95	Good	25.0829320	N	86.5465060	E	Normal

11.10.23 Average DIR - 2682

11/10/23
E.E

Name of Customer: Karik Prasad . Machine no: 19213 , Road: Bambar to Champa Chak Village Road Phase-II , Date: 14-09-23 , Section No: 108 , Equation: $Y = 0.969X + 224.9$



11/10/23
E.E

11/10/23
E.E