

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 2425...../बक्सर

दिनांक- 30/10/23.....

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के
सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति-
2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्न कर
भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि
संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


30.10.23

कार्यपालक अभियंता
ग्रा०का०वि०, कार्य प्रमंडल- बक्सर


30/10/23

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Oct 2023

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 129, dt.-27.09.2023	10129.48905	Certified that out of Rs. 10129.48905Lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 10118.17635 lacs has been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs11.31270 lacs remaining unutilized at the end of the period under.

Total -

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

- 3 **Physical Progress achieved :-**

- Construction of Road works
- Construction of CD works

Executive Engineer

R.W.D. (w) Div. Buxar

AK
30/10/23

Position Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allowed Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)									
1	RM/BU/BU X/22/0013	Dhansoi Sighi Road to Dufia	14191033719	1486 dt08.09.2022	3.269	177.78	97.44635	31.07999	04/A/IBD/2023-24 dt 19.05.2023	18.02.2024	2190	25 mm	5.01%	0	0	95.45782	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS

[Signature]
30.10.23
J.B

[Signature]
30.10.23
A.C

Executive Engineer
RWD (W), Div.- Buxar


[Signature]
30.10.23

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर।

का0आ0स0...2426... बक्सर/ दिनांक...30/10/23

कार्यालय – आदेश


प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत घनसोई सिकठी रोड दुलफा पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10% प्रतिशत, सहायक अभियंता द्वारा 50% एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा, राजपुर


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रशाखा, राजपुर।


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर।

File : H:\memraj_dubey\30101407 - Copy.xls. Section No. : 45. Eqn : $Y = 0.0001X^2 + 0.816X + 249$
 Name of Customer : Mamraj construction Pvt Ltd.. Name of Work/ Road : Dhansoi Singhi Road-Dultia. Lab Job



Forall
 30.10.23
 J.C.

Forall
 30.10.23

For
 30.10.23

Road Name:- Dhansoi Singhi Road-Dulfa Contractor Name:- Mamraj Construction Pvt Ltd.

Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR	IRI/TEGORY	Latitude	ongitude	Event
29/10/23	13:18:0	45	0.1	200	0	2000	2289 G	25.31099	84.12473	Normal	
29/10/23	13:18:29	45	0.1	270	10.1	2700	2769 G	25.31138	84.01134	Normal	$Y = 0 * X^2 + 0.816 * X + 249$ $X = 3100$ $Y = 2778$
29/10/23	13:19:4	45	0.1	300	10.1	3000	3014 G	25.31146	84.01049	Normal	
29/10/23	13:19:4	45	0.1	280	20.2	2800	2896 G	25.31159	84.00951	Normal	
29/10/23	13:19:40	45	0.1	300	10.1	3000	3245 G	25.31172	84.00858	Normal	(R) RURAL ROAD
29/10/23	13:19:40	45	0.1	320	10.1	3200	3456 G	25.31206	84.00783	Normal	Good
29/10/23	13:20:15	45	0.1	380	20.2	3800	3840 G	25.31258	84.00685	Normal	Average
29/10/23	13:20:15	45	0.1	340	20.2	3400	3378 G	25.3127	84.006	Normal	Poor
29/10/23	13:20:50	45	0.1	290	20.2	2900	2965 G	25.31292	84.005	Normal	IRI Value=2999
29/10/23	13:20:50	45	0.1	280	20.2	2800	2899 G	25.31318	84.00405	Normal	Machine ID=415
29/10/23	13:21:26	45	0.1	250	20.2	2500	2542 G	25.31348	84.00304	Normal	
29/10/23	13:21:26	45	0.1	380	30.3	3800	3879 G	25.31099	84.12473	Normal	
29/10/23	13:21:26	45	0.1	330	30.3	3300	3356 G	25.31416	84.00294	Normal	
29/10/23	13:23:11	45	0.1	280	0	2800	2808 G	25.316	84.00354	Normal	
29/10/23	13:23:11	45	0.1	320	20.2	3200	3205 G	25.3161	84.00358	Normal	
29/10/23	13:23:11	45	0.1	270	20.2	2700	2789 G	25.31683	84.00367	Normal	
29/10/23	13:23:47	45	0.1	290	20.2	2900	2986 G	25.31779	84.00379	Normal	
29/10/23	13:23:47	45	0.1	250	20.2	2500	2596 G	25.31867	84.00382	Normal	
29/10/23	13:24:22	45	0.1	280	20.2	2800	2897 G	25.31959	84.00386	Normal	
29/10/23	13:24:22	45	0.1	300	10.1	3000	3012 G	25.3205	84.0038	Normal	
29/10/23	13:24:57	45	0.1	290	20.2	2900	2963 G	25.32144	84.0039	Normal	
29/10/23	13:24:57	45	0.1	280	10.1	2800	2873 G	25.3224	84.00406	Normal	
29/10/23	13:25:32	45	0.1	240	10.1	2400	2456 G	25.32323	84.00431	Normal	
29/10/23	13:26:8	45	0.1	270	10.1	2700	2789 G	25.32413	84.00457	Normal	
29/10/23	13:26:8	45	0.1	280	20.2	2800	2896 G	25.32499	84.00485	Normal	
29/10/23	13:26:43	45	0.1	320	20.2	3200	3245 G	25.32575	84.00529	Normal	
29/10/23	13:26:43	45	0.1	330	20.2	3300	3396 G	25.32698	84.00596	Normal	
29/10/23	13:27:18	45	0.1	310	20.2	3100	3197 G	25.32698	84.00596	Normal	
29/10/23	13:27:18	45	0.1	290	20.2	2900	2987 G	25.32735	84.00614	Normal	
29/10/23	13:27:54	45	0.1	245	30.3	2450	2456 G	25.3297	84.00752	Normal	
29/10/23	13:27:54	45	0.1	280	30.3	2800	2896 G	25.33248	84.00795	Normal	

Handwritten signature and date: 30/10/23 J.E.

Handwritten date: 30/10/23