

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd and final bill					
ABSTRACT OF COST					
(1) Clearing & grubbing & dry side T.M.B P-(25) item. (1)					
$50.524 \text{ m}^2 @ 58709.27/1100$					311162
(2) Contn. to subgrade & dry side T.M.B P-(25) item. (2)					
$= 880.19 \text{ m}^2 @ 238.02/1100$					209503
(3) Contn. to good curbs & dry side T.M.B P-(25) item. (3)					
$= 53.076 \text{ m}^2 @ 216.94/1100$					112677
(4) P.V. work curbs & dry side T.M.B P-(25) 47.086 m ²					
$@ 4647.70/1100$					218851
(5) P.V. work curbs & dry side T.M.B P-(25) item. (5)					
$= 74.62 \text{ m}^2 @ 4483.89/1100$					334588
(6) P.V. Prime Coat (551) & dry side T.M.B P-(25) item. (6)					
$995.07 \text{ m}^2 @ 59.08/1100$					58789
(7) Patch repair M.S type B & dry side T.M.B P-(25) item. (7)					
$= 1083.95 \text{ m}^2 @ 249.95/1100$					270933
(8) P.V. Base Coat (251) & dry side T.M.B P-(25) item. (8)					
$= 4300.25 \text{ m}^2 @ 20.05/1100$					86220
(9) P.V. SDBC & dry side T.M.B P-(25) item. (9)					

Scanned with OKEN Scanner