

આવશ્યક મમલસય તથા હે રજાવિષયે મળિય એણે નવ

મમલસય (સે)

Schedule XLV-Form No. 134

વવર DIVISION

ફે 21/67 SUB-DIVISION

MEASUREMENT BOOK

1569

સાવકાન :- સાવકા કુમાર એક

38/582
2620-21

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/W - Alampur Mangsy Road to Rakasya Yadav Tola					
Agency - Sri Sankar Kanchan Day Indlaw, Bhuber					
Age No - 289 BD / 2020-21					
Date of Est - 06-08-22					
① Restoration of Drain					
Cuts -					
$2 \times 30.00 \times 1.125 \times 0.300 = 20.25 \text{ m}^3$					
$2 \times 12.00 \times 1.125 \times 0.300 = 11.475 \text{ m}^3$					
					<u>31.725 m³</u>
② Making up of Berms / Shoulder - all					
$2 \times 3 \times 30.00 \times 1.125 = 202.50 \text{ m}^2$					
$2 \times 2 \times 6.00 \times 1.125 = 58.50 \text{ m}^2$					
					<u>261.0 m²</u>
③ Repair of Pot. Holes with 20 mm MS - all					
$11 \times 1.25 \times 1.1 = 15.26 \text{ m}^2$					
④ Maintenance of CD Wall 3.0 m					
⑤ Maintenance of Canal Slop 0.03 km					
⑥ Maintenance of 2000 kg for					

Continuation 0.11 / km

Continuation

0.11 km

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Maintenance (D) / Work 3. m/s Vb - (63)					
				1130 = 62/2000	3392
(5) Maintenance Biology 0.03/cm Vb - (83)					
				1080 = 23/100	101
(6) Maintenance of 200 m 2 1 cm Stone					
				0.1/1 cm Vb - (63)	
				482 = 55/100	542
(7) (a) Maintenance of grounds (b) Trees and Shrubs					
				2.0 m/s Vb - (63)	
				100 = 93/100	252
(8) Maintenance of grounds (a) Trees and Shrubs					
				7.0 m/s Vb - (63)	
				6 = 23/100	42
(9) Maintenance of grass and weeds -					
				15.76 m/s Vb - (69)	
				2 = 24/100	35
(10) Maintenance of waste land -					
				53.58 m/s Vb - (64)	
				16 = 34/100	825
					34588
					4182
					2462
					38986
					9823
					29173

Continuation

2nd Year maintenance

67

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
W/L - Alambur mmsy Road to Rakiga Madu Tola					
W/L - Srs Sontag to Charbey Fndm					
W/L - 28530/2020-21					
W/L - 22-07-23					
① Restoration of Road					
2x30.0x1.125x0.300=20.25m ³					
2x26.0x1.125x0.300=19.55m ³					
					39.80m ³
② making up of Berms 2 skidways					
2x4x30.0x1.125=270.0m ²					
2x20.0x1.125=45.0m ²					
					315.0m ²
③ Refurb of Pot holes with 200mm mss all cans					
11x1.5x1.75=30.415m ²					
④ maintenance of column					
3.0m ³					
⑤ maintenance of Road Sy					
0.11 km					
⑥ maintenance of 200m ² Kms Str					

Continuation

0.14 km

Sch. XLV-Form No. 134

69

42891=

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Maintenance of Road Sprm					
Q. 11 km ar p-60					
		1080=23	1 km	121=	
(6) Maintenance of 200m Q					
1 km Sprm					
Q. 12 km v p-62					
		482=55	1 km	62=	
(7) (i) Cult of branches of trees and shrubs					
2.0 m S v p-68					
		100=99	1 km	202=	
(ii) Cult of shrubs from					
10.0 m S v p-68					
		65=23	1 km	42=	
(iii) Trimming of grass					
and weeds					
18.0 m S v p-68					
Q. 11 km - 16.0 m					
		2=24	1 km	36=	
(8) H.R. te. Washing of Dargah					
Walls of CD					
64.575 m ² v p-68					
11 km - 63.0 m ²					
		16=23	1 km	1029=	
				44093=	
Add 1/65				5291=	
Add 1/60				441=	
				49825=	
Loss 25.19% below 15				12551=	
				37224=	

Continuation