

| Particulars                                   | Details of actual measurement |    |    |                    | Contents of area |
|-----------------------------------------------|-------------------------------|----|----|--------------------|------------------|
|                                               | No.                           | L. | B. | D.                 |                  |
| 4th year Maint <sup>n</sup>                   |                               |    |    |                    | (Abstract)       |
| Work: NH 101 (B.D.S. Public School)           |                               |    |    |                    |                  |
| Kethupura to Kishumpura                       |                               |    |    |                    |                  |
| Dalashin to G.                                |                               |    |    |                    |                  |
| — GTSNY                                       |                               |    |    |                    |                  |
| Survey: Vijay Singh & Kantaraj, Petne         |                               |    |    |                    |                  |
| N/G: 83/GTSNY/SGD/18-19                       |                               |    |    |                    |                  |
| Date of construction                          |                               |    |    | 16.10.19 (4 p.m.s) |                  |
| ① Restoration of rain cul -                   |                               |    |    |                    |                  |
| — all as per TL & Dist <sup>n</sup>           |                               |    |    |                    |                  |
| of E/c                                        |                               |    |    |                    |                  |
| Qty = 52.107 m <sup>3</sup> V.M.B. 1/16       |                               |    |    |                    |                  |
| @ 262.321 m <sup>3</sup> = 17228 =            |                               |    |    |                    |                  |
| ② Maint <sup>n</sup> of center shoulder       |                               |    |    |                    |                  |
| — do —                                        |                               |    |    |                    |                  |
| Qty = 208.95 m <sup>3</sup> V.M.B. 1/16       |                               |    |    |                    |                  |
| @ 56.05 / m <sup>3</sup> = 11712 =            |                               |    |    |                    |                  |
| ③ Maint <sup>n</sup> of H.P.C. — do —         |                               |    |    |                    |                  |
| Qty = 2.108 m <sup>3</sup> V.M.B. 1/16        |                               |    |    |                    |                  |
| @ 1092.62 / m <sup>3</sup> = 2187 =           |                               |    |    |                    |                  |
| ④ Maint <sup>n</sup> of road sign — do —      |                               |    |    |                    |                  |
| Qty = 0.61 km V.M.B. 1/16                     |                               |    |    |                    |                  |
| @ 1057.08 / km = 6342 =                       |                               |    |    |                    |                  |
| ⑤ Maint <sup>n</sup> of 20m & 4m stone — do — |                               |    |    |                    |                  |
| Qty = 0.2 km V.M.B. 1/16                      |                               |    |    |                    |                  |
| @ 720.4 / km = 144 =                          |                               |    |    |                    |                  |
| ⑥ Cutting of shrubs trees — do —              |                               |    |    |                    |                  |

Continuation

Continuation