

5th year maintenance.

47

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work - Main ⁿ at Road from					
Lowy se Harpur Horilke					
Bhumihar, Harpur + 19.					
N/A:- Vijay Kumar Singh.					
App. NO:- 33 SBD/ 2018-19					
D.O.S-	11.	09.	2018		
A.D.O.C-	07.	05.	2019		
Date of measurement.					
(V ₁) Restoration of rain					
Cuts do do - e/i					
2x 7.50x 0.90x 0.30 =					4.05m ³
2x 8.00x 0.80x 0.30 =					3.84m ³
5x 9.50x 0.50x 0.30 =					7.125m ³
3x 8.00x 1.20x 0.30 =					8.64m ³
2x 7.10x 1.10x 0.30 =					4.620m ³
5x 9.00x 0.50x 0.30 =					6.75m ³
					Qty = 35.025m ³
					Limit Qty = 34.26m ³
(2/2) main ⁿ of earthen					
Shoulder do do - e/i					
4x 7.00x 1.10 =					30.80m ²
3x 8.00x 0.90 =					21.60m ²
5x 9.00x 1.10 =					49.50m ²
5x 8.00x 1.20 =					48.00m ²
5x 8.00x 0.90 =					36.00m ²
					Continuation Qty = 185.90m ²

50

ch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/F	RS2	271312W
less below			10Y.	RS(-)	27132W
				RS2	24418200
15/4/24 SE		Uindit	15/4/24	DE	