

| Particulars                                                 | Details of actual measurement |      |      |    | Contents of area      |
|-------------------------------------------------------------|-------------------------------|------|------|----|-----------------------|
|                                                             | No.                           | L.   | B.   | D. |                       |
| Name of work, point of road from Doudali to Keshjee Colony. |                               |      |      |    |                       |
| Agency - Survey by Keshjee Colony                           |                               |      |      |    |                       |
| Agreement no. 63100/2016/19.72                              |                               |      |      |    |                       |
| Actual completion. 02.08.2020.                              |                               |      |      |    |                       |
| Record Entry                                                |                               |      |      |    |                       |
| ① Restoration of road with soil - do -                      |                               |      |      |    |                       |
| 7x                                                          | 4.50                          | 1.10 | 0.30 |    | 13.97                 |
| 6x                                                          | 5.60                          | 0.90 | 0.30 |    | 9.02                  |
| 8x                                                          | 4.40                          | 0.80 | 0.30 |    | 8.45                  |
| 12x                                                         | 4.60                          | 0.85 | 0.30 |    | 14.08                 |
| 6x                                                          | 6.90                          | 0.95 | 0.30 |    | 11.30                 |
| 9x                                                          | 5.30                          | 0.70 | 0.30 |    | 10.02                 |
| 8x                                                          | 4.55                          | 0.95 | 0.30 |    | 10.37                 |
| Total =                                                     |                               |      |      |    | 77.16 m <sup>2</sup>  |
| ② point of road                                             |                               |      |      |    |                       |
| Shoulder - do -                                             |                               |      |      |    |                       |
| 2x 9x                                                       | 4.80                          | 0.20 |      |    | 69.12                 |
| 2x 6x                                                       | 5.90                          | 0.20 |      |    | 49.56                 |
| 2x 7x                                                       | 4.60                          | 0.90 |      |    | 57.96                 |
| Total =                                                     |                               |      |      |    | 176.64 m <sup>2</sup> |
| ③ Repair of pot holes                                       |                               |      |      |    |                       |
| 4x                                                          | 5.60                          | 0.60 |      |    | 13.44                 |

12/11/23  
RC

Continuation

| Particulars             | Details of actual measurement |    |    |    | Contents of area |
|-------------------------|-------------------------------|----|----|----|------------------|
|                         | No.                           | L. | B. | D. |                  |
| (1) cutting of bonder   |                               |    |    |    |                  |
| of door - do -          |                               |    |    |    |                  |
| 08 nos wide page - (88) |                               |    |    |    |                  |
| ch. 108.52/each         |                               |    |    | Rs | 639              |
|                         |                               |    |    | Rs | 227109           |
| Cess 1.01% of 62000     |                               |    |    | Rs | 3353             |
|                         |                               |    |    | Rs | 223756           |

  
 12/11/25  
 RE

| Material used  |   |       |                |
|----------------|---|-------|----------------|
| Earth work     | — | 27.16 | m <sup>2</sup> |
| Bitumen 5% -   |   | 136   | kg             |
| Drum/skin Re-1 |   | 16    | kg             |
| stone chips -  |   | 1.71  | m <sup>2</sup> |
| crust of saw - |   | 0.38  | m <sup>2</sup> |

  
 12/11/25  
 RE