

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
names of more main st road from Harpur chauri to Harpur primary school.					
Agency - Maa subhadr megha					
19/11/2021					
Agreement no - 104500/mmbh/19.20					
Actual Completion - 25.04.2021					
Record					
1) Restoration of soil					
cuts with soil					
12 x 4.60 x 1.10 x 0.30					18.12
9 x 5.80 x 1.05 x 0.30					16.44
8 x 6.60 x 1.00 x 0.30					15.84
7 x 5.90 x 0.90 x 0.30					14.34
8 x 6.70 x 0.95 x 0.30					15.28
9 x 5.90 x 1.10 x 0.30					16.04
16 x 4.90 x 0.80 x 0.30					18.82
6 x 6.80 x 0.85 x 0.30					10.40
14 x 3.75 x 0.95 x 0.30					14.96
total					140.34
2) making up berms					
shoulders excess soil					
2 x 16 x 6.80 x 0.95					206.72
2 x 18 x 4.90 x 0.90					158.76
2 x 12 x 7.40 x 0.85					150.96
2 x 14 x 5.90 x 0.80					132.16
2 x 9 x 9.65 x 1.05					182.39
2 x 16 x 6.20 x 0.80					158.72
total					989.71

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Rebuilding of main cut with soil -					
140.34 m ² note Page (58)					
est 379.59/m ²				4	53272
2) Making up Borers/ Shoulder excess soil					
989.71 m ² note Page (58)					
est 57.01/m ²				4	56423
3) Repair of pot holes - do -					
156.54 m ² note Page (59)					
est 411.21/m ²				6	64386
4) Patch repair over bituminous surface					
156.54 m ² note Page (59)					
est 229.57/m ²				4	43764
5) Maint of road B. J. on - do -					
1.420 km note Page (59)					
est 1054.28/km				4	1492
6) Maint of 200 m/s K. H. stone -					
2.830 km note Page (59)					
est 688.12/km				4	1948
7) Cutting of branches of trees -					
0.5 m/s note Page (59)					
est 106.52/m/s				4	533

[illegible]