

3rd year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
name of work -					
from Pm by to Brijgi dik					
Agency -					
Arbind kumar singh					
Agreement no -					
106509/mmbay/19.20					
Actual Completion -					
25.04.2021					

Record Entry					
1/1	Restoration of roia				
	Work with soil -				
	9	5.40	0.80	0.30	11.66
	6	6.30	0.95	0.30	10.72
	8	5.40	1.05	0.30	14.82
	7	4.80	1.10	0.30	11.07
	6	5.85	0.90	0.30	9.48
	9	4.70	1.00	0.30	12.69
	12	3.70	0.70	0.30	9.32
	16	4.10	0.75	0.30	14.76
	8	4.25	1.125	0.30	11.48
				Total	106.12

2/2	making up Berms				
	shoulders filled soil -				
	2	12	4.80	0.90	103.68
	2	9	6.60	0.80	95.04
	2	8	5.90	0.85	80.24
	2	16	5.40	0.95	164.16
	2	14	4.85	0.80	108.64
	2	18	4.80	1.10	190.08

Continuation

Total 741.84

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4/5) Patch repair over bituminous surface					
118.13 m ² wide Page (54)					
at 279.52/m ²				h	33026
5/17) Point of survey signs - do					
1.060 m ² wide Page (54)					
at 1054.28/m ²				h	1118
6/10) Point of survey 124 stone					
2.130 m ² wide Page (54)					
at 688.12/m ²				h	1466
7/2) Cutting of branches of trees					
0.4 m ² wide Page (54)					
at 106.52/m ²				h	426
8/11) Trimming of grass & weeds - do					
9668.00 m ² wide Page (54)					
at 2.12/m ²				h	3620
9/11) Point of trees by 000.0					
166 m ² wide Page (55)					
at 561.46/m ²				h	93202
				Rs	266020 264020
Add GST 12.1.				Rs	31682
Add L.C. 1.1.				Rs	2640
				Rs	298342
Less 0.02 m ² below				Rs	60
				Rs.	298282

15.4.24. Continuation