

2nd year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Named	House: Corner station of Kanja				
	Jailpur road Nandade Kedur				
	Mishra ke Ghar to Repura				
	Nandade Kedur take under MNGS				
Assess:	Nandade Kedur				
Assess:	28/5/2017-18				
Actual Date of	Completion: 12.07.18				
Item 1	Restoration of edge cut - 75				
	10x	30.00x	0.60x	0.20x	36.00 m ³
	7x	5.50x	0.60x	0.30x	9.90 "
	5x	15.00x	0.75x	0.20x	11.25 "
	6x	30.00x	0.45x	0.40x	46.80 "
			Total		103.95 "
Item 2	Maintenance of center shoulder - 75				
	10x	30.00x	0.45x		135.00 m ³
	10x	30.00x	0.40x		120.00 "
	10x	30.00x	0.45x		135.00 "
	6x	30.00x	0.80x		144.00 "
	2x	30.00x	0.60x		36.00 "
			Total		570.00 "
Item 3	Maintenance of stone pipe culvert.				
			1x 4m x 3m		4 m ³
Item 4	Maintenance of stability of culvert				
Item 5	Maintenance of road sides - 75				
			1x 1.78 km		1.78 km
Item 6	Trimming of grass & weeds				

Continuation

Continuation