

3rd Year Maintainer

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- R.W.D. Road High School to Kwarpathi Nartole					
Agency:- Sri Pavan Kr. Mishra					
App. No.- 20 SB-2/2018-19.					
Date of W.O.- 26/6/2018.					
Date of Actual Completion:- 16-11-19.					

① Restoration of Road Cut

8x	12.00x0.80x0.30	23.04m
10x	16.00x0.80x0.30	38.40
12x	8.00x1.00x0.30	28.80
7x	12.00x1.00x0.30	25.20
7x	14.00x1.00x0.30	29.40
3x	7.00x0.60x0.30	3.28
		148.62m

② Making up Berms/ Shoulder with soil. do sell

5x	30.00x0.80	120.00m
7x	20.00x0.80	112.00m
6x	15.00x1.00	90.00
8x	12.00x1.00	96.00
2x	30.00x0.80	144.00
3x	25.00x0.80	60.00
5x	18.00x0.80	72.00
2x	7.00x1.00	14.00
		708.00m

Sch. XLV—Form No. 134

Particulars	Quantity of material consumed				Continuation of Bill
	No	1	2	3	
Abutment of culvert					
(1) Restoration of R.C.C. culvert					
148.62 m ³ dry rock (31)					
Qd 341 = 77/m ³ 150786 =					
(2) Restoration of Berms/Shoulder with soil					
708.00 m ² dry rock (31)					
Qd 10 = 59/m ² 35818 =					
(3) Repair of pot holes					
75 mm B.M. for cell					
6.85 m ³ dry rock (32)					
Qd 10280 = 83/m ³ 70424 =					
(4) Patch Repairs over pot holes					
91.40 m ² dry rock (32)					
Qd 81 = 84/m ² 7480 =					
(5) Patch Repairs over bitumen surface					
do all.					
91.40 m ² dry rock (32)					
Qd 72 = 49/m ² 6626 =					

Continuation

18 171139 =

Continuation

Scanned with CamScanner