

3rd year Maintenance Bill

59

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W- Main ⁿ of Road from Kudhori					
Baliya Path Railway					
Gumti to Bangra Bansidhar					
Muslim dala					
Agency - Manjeet Kumar					
Kankarbagh Patna-20					
Agreement No - 26/SB0/2019-20					
Date of work order - 20/05/2019					
Date of completion - 19/02/2020					
Actual Date of completion 15/09/2020					
Measurement					
(15.1) Restoration of					
Rain cuts - - E12					
$8 \times 2.75m \times 1.10m \times 0.30m = 7.26 m^3$					
$9 \times 1.75m \times 1.20m \times 0.40m = 7.56 m^3$					
$8 \times 1.80m \times 1.20m \times 0.30m = 5.184 m^3$					
$8 \times 3.0m \times 0.85m \times 0.3m = 6.12 m^3$					
$9 \times 2.75m \times 1.20m \times 0.30m = 8.91 m^3$					
$5 \times 1.20m \times 0.80m \times 0.3m = 1.44 m^3$					
Total Qty = 36.474 m ³					
(15.2) Maintenance of Earthen					
Shoulder - - - E12					
$6 \times 2 \times 5.0m \times 1.0m = 60.0 m^2$					
$8 \times 2 \times 4.0m \times 0.95m = 60.8 m^2$					
$7 \times 2 \times 4.90m \times 1.0m = 68.6 m^2$					
$3 \times 2 \times 3.50m \times 0.80m = 16.8 m^2$					
Total Qty = 206.20 m ²					

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
35.29 m ² Qty vide TMB p.no (60)					
@ 241.93/m ²				RS=	8538.00
(15.3)(ii) Patch repair on already filled pot holes - - E/I					
Same Qty item no (15.3)(iii)(a) vide TMB p.no (60)					
@ 293.95/m ²				RS=	10374.00
(8.13) Providing and laying of hot appli/- - F/I					
148.0 m ² Qty vide TMB p.no (60)					
@ 755.53/m ²				RS=	111818.00
(15.7) Maintenance of Culverts - - E/I					
2.00 Km Qty vide TMB p.no (60)					
@ 2309.03/Km				RS=	4618.00
(15.11) Maintenance of 800mm 8					
Km Stone - - E/I					
0.74 Km Qty vide TMB p.no (61)					
@ 735.27/Km				RS=	544.00
Total				RS=	161856.00
Below ex. As per Agmt RS(-)=					3237.00
Total				RS=	158619.00
18/12/22 SE					
Continuation					