

4th Year Maintenance

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Bhagwati Tola to Tola under UTSNY					
Agency- M/S Maq Sihasani Construction					
Agreement No-24 SBD/2018-19					
Date of start- 22/10/2018					
Date of completion- 21/10/2019					
Actual date of completion- 29/03/2019					
4 th Year Maintenance					
Period					
① Maintenance of earthen shoulder					

3	X	6.00	X	0.75	=	13.50 m ²
4	X	7.50	X	1.25	=	37.50 m ²
5	X	6.50	X	1.32	=	42.90 m ²
4	X	6.00	X	1.25	=	30.00 m ²
3	X	9.50	X	1.20	=	34.20 m ²
5	X	11.50	X	1.28	=	73.60 m ²
2	X	5.50	X	0.90	=	9.90 m ²
						241.60 m ²
② Restoration of Ruineity						
3	X	10.00	X	1.20	X	0.25 = 9.00 m ²
5	X	7.00	X	1.25	X	0.30 = 13.12 m ²
4	X	8.00	X	1.30	X	0.30 = 12.48 m ²
3	X	7.50	X	1.15	X	0.25 = 6.47 m ²
5	X	9.00	X	1.25	X	0.30 = 16.87 m ²
2	X	12.00	X	0.90	X	0.30 = 6.48 m ²
						64.42 m ²
Continuation						

Abstract of cost

Sch. XLV-Form No.134

52

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Raincut					
Q-V7113 P 49 ②			64.4217		
P 50 ③			29.0517		
P 51 ④			32.4517		
			125.9217		
e R 365 = 25/17 R 45992 = 0					
② Maintenance of earthen					
Shoulder					
Q-V7113 P 49 ①			241.6017		
P 50 ③			246.3717		
P 51 ④			211.9017		
			699.8717		
e R 54 = 37/17 R 38052 = 0					
③ Maintenance of H.P.					
culvert					
Q-V7113 P 50 ⑤			3		
e R 113 1.64/each R 33952 = 0					
④ Maintenance of 200 m					
Stone					
Q-V7113 P 50 ⑥			1.750 Km		
e R 740 = 27/Km R 1295 = 0					
R 88, 734 = 0					
1.225 0.22/1 below →					
R 88, 539 = 0					
for 15/4/23					
for 16/04/23					
AE					

Continuation