

1st year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: Lops Pokhar to Sewalchika Nurfara under mmsy					
2. Name of Agency: Abhar Kumar Thakur					
3. Agreement No: 05/SBD/2021-22					
4. Approval of rate: 0.08% below					
5. Actual dt. of Completion: 23.01.2023					
— Work done —					
① Restoration of rain cuts					
1st st with soil surface					
1x	20.50	x	0.30	x	0.30 = 3.075
1x	18.90	x	0.45	x	0.30 = 2.55
1x	20.80	x	0.58	x	0.30 = 3.619
2x	30.00	x	0.58	x	0.30 = 10.44
2x	30.00	x	0.48	x	0.30 = 8.640
3x	30.00	x	0.45	x	0.30 = 24.30
					12.15
1x	18.90	x	0.50	x	0.30 = 2.835
1x	18.90	x	0.44	x	0.30 = 2.495
					Qty = 45.805m
					Say Qty = 45.06m
② maintenance of earthen					
1st st Shoulder surface					
2x	30.00	x	0.45		= 81.0
1x	30.00	x	0.52		= 15.60
1x	20.60	x	0.50		= 10.30
1x	10.50	x	0.48		= 5.04
1x	20.60	x	0.60		= 12.36

C.O Qty = 124.30m²
Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			R ₁	43389	= ∞
Add 1% Labourcess				439	= ∞
Add 12% Crst.				5206	= ∞
Seismioagefee			R ₁	110	= ∞
			R ₁	49134	= ∞
Less 0.08% Selum			C, B	38	= ∞
			R ₁	49095	= ∞

Ram
 24.02.2024
 J.E.
 (W) 24/2/2024
 R₁

Material Statement

(i) Earth	—	82.61m ³
(ii) Bitumen 50	—	44.0kg
(iii) Stone chips	—	0.563m ³

Ram
 24.02.2024
 J.E.
 (W) 24/2/2024
 R₁