

3rd year maintenance

51

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work	Gandapur Piprur				
mykhya sadak to Bahadurpur					
Crack					
2. Name of Agency	Ramanand Thakur				
3. Agreement No.	61 SBD/2020-2021				
4. Actual of Completion	23.03.2021				
— measurement as below —					
① Restoration of drain cuts with					
15% soil sub fill					
4 x 30.0 x 1.0 x 0.30 =					36.0
5 x 30.0 x 1.0 x 0.30 =					45.0
1 x 20.60 x 0.80 x 0.30 =					4.944
1 x 30.0 x 0.75 x 0.30 =					6.75
3 x 20.50 x 0.85 x 0.30 =					31.265
					Qty = 108.376 m ³
					Say Qty = 104.19 m ³
② maintenance of earthen					
15% shoulder sub fill					
2 x 5 x 30.0 x 0.80 =					240.0
1 x 20.60 x 0.75 =					15.45
1 x 20.90 x 0.68 =					14.212
1 x 30.0 x 0.70 =					21.0
2 x 4 x 30.0 x 0.68 =					163.20
1 x 30.0 x 0.50 =					15.0
2 x 30.0 x 0.65 =					39.0
2 x 30.0 x 0.60 =					36.0
2 x 17.50 x 0.50 =					17.50
2 x 17.60 x 0.52 =					18.387
Continuation					Qty = 579.749 m ³
					Say Qty = 578.81 m ³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BFB 509508 = m
⑥ maintenance of by the road side					
— all F.R.					
Qty = 147.01 m ² side					
TM 13 page (53)					
⑦ 550 = 01/each - R					8673 F
⑦ maintenance of 157 slab type culvert					
— all F.R.					
Qty = 1.0 No side					
TM 13 page (53)					
⑧ 2394 = 96/Rock - R					2395 = m
⑧ maintenance of 15.11 200 m & 1 km & 1 me					
— all F.R.					
Qty = 2.270 km side					
TM 13 page (53)					
⑨ 748 = 22/Km - R					1698 = m
					R 600332 = m
Add 1/2 Lab work - R					6003 = m
Add 12.1 G.S.T - R					72040 = m
Storage fee - R					1184 = m
					R 479559 = m
					678575 = m
RM 26.02.2017 J.E.					

Continuation

Value of Rock supplied : Rs.