

2nd year maintenance Bill

Schedule XLV-FORM No. 134

58

Schedule XLV-FORM NO. 15					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Name of Road		chaka chapra Gungach's			
		chapra to manager Rana			
		Ke Chak Tak in Mmabur			
		Black - under Mmasy (SC)			
Agency	Randhir Namal				
Agreement No	Mmasy/SBD/44/2018-19				
Date of work order	21/12/2018				
Actual date of completion	30.4.2021				

Defailed works

(1)	Restoration of Rannach				
	WIR	2018		all	
	comple	100	(av)	90	
	25	2.00	1.10	0.30	= 16.50 m ³
	15	1.90	0.90	0.30	= 7.70 "
	10	1.30	0.80	0.30	= 3.12 "
	10	1.50	1.00	0.30	= 5.85 "
	16	1.70	1.20	0.30	= 9.79 "

	10	2.00	1.10	0.30	= 6.60 "
	12	1.85	1.05	0.30	= 6.99 "
	4	1.20	1.00	0.30	= 1.44 "
					= 57.99 m ³

(2) Maintenance of Earthen

Shoulders stoppings & excess

2018 - all complete

2	4	20.00	1.00		= 240.00 m ²
2	2	20.00	1.02		= 81.60 "
					= 321.60 m ²

(3) Patch repairs with soil

Soil surface type B

5	2.00	1.50			= 15.00 m ²
4	2.00	2.00			= 16.00 "
2	2.00	1.00			= 4.00 "
					= 35.00 m ²

Continuation

Schedule XLV-FO

Details of actual measurement			
Particulars	No.	L.	B.
③ Patch repairs with type B			
Qty vide P-58			
= 25 m ² ch		273.19 / m ²	R 9542
④ maintenance of H.P. culvert			
Qty vide P-59			
= 2 Nos ch		1131.64 / each	R 3395
⑤ maintenance of Road			
Qty vide P-57			
= 0.956 km ch		1037.63 / km	R 1040
⑥ maintenance of 200m			
Qty vide P-57			
= 0.143 km ch		138.55 / km	R 106
⑦ cut of 2 shrubs			
Qty vide P-59			
= 5 Nos ch		107.43 / each	R 537
⑧ removal of grasses & weeds			
Qty vide P-59			
= 161.53 m ² ch		2220 / m ²	R 356
⑨ white wash of parapet walls of H.P. culvert			
Qty vide P-59			
= 12.93 m ² ch		21.81 / m ²	R 291
			R 54826
			54796
			54826

17/3/2017
 17/3/2017
 Continuation
 23.3.24