

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year main					
Repair of Road - near hospital to					
Punarnagar Bazar					
Agency - M/s Lalab Singh					
Date of Start -		14/8/15			
Date of completion		13/8/16			
Agreement No		67 sub/275/16			

Measurement

Qty Restoration of side cuts -

$$2 \times 5 \times 30.00 \times 1.125 \times 0.300 = 101.25$$

$$2 \times 5 \times 30.00 \times 0.90 \times 0.300 = 81.00$$

$$2 \times 1.15 \times 0.65 \times 0.300 = 2.79$$

185.04

Qty Making up loss of material / Irregularities -

$$2 \times 10 \times 30.00 \times 1.125 \times 0.300 = 675.00$$

$$2 \times 4 \times 30.00 \times 0.90 \times 0.300 = 228.00$$

$$2 \times 2 \times 30.00 \times 1.00 \times 0.300 = 120.00$$

$$1 \times 5.00 \times 0.75 \times 0.300 = 3.75$$

1026.75 m²

Qty Repair to Pot holes and removal of loose material during of - - - 217

$$2 \times 30.00 \times 1.90 \times 0.300 = 114.00$$

Qty Patch repair on already tiled Pot h with 75mm N.B.M Gr-II - - - 212

Glyvide T.H.B page no. Item no. 32114.1

Qty Maintenance of hem pipe culvert - -

2.00 Nos

Qty Maintenance of slab type culvert -

2.00 Nos

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ans Maintenance of kerbside					
renewal of by way of				- 11	
wide kerb w - 50					
2.00 km c b 875.02 / No 20					1750.00
Ans Maintenance of slab type.					
renewal by way of				- 11	
wide kerb w - 50					
2.00 km c b 1831.44 / No 20					3663.00
Ans Maintenance of 200 m x 2 km					
stone by way of refilling -					
wide kerb w - 51					
2.500 km c b 574.06 / km 25					1435.00
				619090.5 = w	
Less for 5% discount				619091.20	
				4171814.20	

Prepared by
22/05/2020
A2

Sanjay Kumar
18/05/2020
J.E