

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work:-	Primary school to Bhangho Tola,				
	Noon Nadi talu.				
Agency:-	Reckon En Enps. del.				
Agreement:-	135 (SAD) 2018-19				
Actual date of completion:-	18/08/19				
① Restoration of structure.					
	4	20.0	0.75	0.30	24.0 m ³
	10	3.0	1.0	0.30	9.0 m ³
	05	5.0	0.90	0.20	6.75 m ³
	8	2.5	0.75	0.30	4.50 m ³
					<u>38.25 m³</u>
					at 38.07 m ³
② maintenance of another					
Shredder					
	4	15.0	1.0		60.0 m ²
	8	10.0	0.90		72.0 m ²
	4	5.0	1.0		20.00
	8	11	0.25		66.00
					at 211.50 m ²
③ Repair to P.T. holes					
with mss.					
	4	3.0	1.0		12.0 m ²
	6	2.0	1.5		18.0 m ²
	4	3.5	1.0		14.0 m ²
					44.0 m ²
④ Patch repair to P.T.					
holes					
	3	3.0	1.0		9.0 m ²
	4	2.0	1.5		9.0 m ²
	4	3.75	1.5		22.50
	1	4.0	1.0		4.0 m ²
					at 44.06 m ²
					44.50 m ²

Continuation