

7.7.7 Maintenance

55

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Name of work -		M.R.D.A road to P.Needy			
		Kharling Madhav Borotayalegarh			
(2) Name of Agency -		M.P.O. Karmi Roshan			
		Sudhansu Madhopur, Nowrangpur			
(3) Ag. No. -		M.P.O./TSB/53/2018-19			
(4) Actual date of construction work		Completed - 06-01-2020			
		work done			
(5) Restoration of roads in					
		48 x 3.45 x 0.85 x 0.60 = 24.46 m <sup>3</sup>			
(6) Maintaining surface					
		230 320 x 0.80 2 552 m <sup>2</sup>			
(7) Repair to Pot holes					
		5 4.95 x 2.70 - 66.83 m <sup>2</sup>			
		2 x 7.85 x 2.30 - 36.11 m <sup>2</sup>			
		102.94 m <sup>2</sup>			
415 patch repair					
		Area vide 415(5) - 102.94 m <sup>2</sup>			
		250 X 1000			

Continuation

**Sch. XLV-Form No. 134**