

4 year maintenance Bill

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of the Road-	Harkariya Laldevi se Ram -				
	Post Das Math Gora Barua in somepur Block.				
Agency-	Ranchin Kumar, Belahi Lachchi Minapur somepur				
Agreement No-	M79033/SD-45/2018-19				
Actual date of Completion-					
Details of work					
① Restoration of Rainwater	Sole - all complete job				
	23x	1.50x	0.80x	0.30	8.28 m ³
	27x	1.30x	1.00x	0.30	10.53
	20x	1.70x	1.30x	0.30	13.26
	11x	2.00x	0.85x	0.30	5.61
	23x	1.90x	0.70x	0.30	4.18
	25x	2.00x	0.90x	0.30	13.50
	17x	2.20x	0.80x	0.30	8.98
	13x	2.50x	1.00x	0.30	9.75
	5x	1.90x	0.95x	0.30	2.71
					= 88.15
					88.05 m ³
② Maintenance of Barren	Shoulder with footpath				
	as per spec of 8/10				
	6x2x	30.00x	1.10		= 396.00 m ²
	3x1x	30.00x	1.00		= 90.00
Continuation					= 486.00 m ²

15/12/24

MATERIAL STATEMENTS -

①	Earth -	88.05 m ³
②	fine metal -	6.53 m ³
③	sf concrete -	1.30 m ³
④	fine chips -	1.94 m ³
⑤	portland cement -	0.14 m ³

15/12/24

Continuation