

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
Work to	Panchayat Bahawan Dubla to Yadan					
	to Kamal das ke ghaz tak					
Agency to	Ramanand Thakur.					
Agreement	31/11/2018-19					
Date of Actual completion	15/01/19.					
①	Restoration of drain					
	cuts.					
cu	5	20.0	1.0	0.30	30.0m ³	
	4	15.0	0.70	0.20	16.20m ³	
	18	3.5	1.0	0.35	22.05m ³	
	6	7.0	1.25	0.40	21.00m ³	
	10	5.0	0.75	0.30	11.25m ³	
	10	2.5	1.0	0.375	9.375m ³	
	22	4.0	0.75	0.40	26.40m ³	
	18	2.0	1.0	0.40	14.40m ³	
	2	5.0	0.40	0.35	3.15m ³	
					153.825m ³	
②	maintenance of earthen Shoulder					
cu	4	2	30.0	1.0	240m ²	
	10	15.0	1.0		150.0m ²	
	8	20.0	1.0		160.0m ²	
	6	12.0	0.90		64.80m ²	
	15	10.0	0.75		112.50m ²	
	10	15.0	0.90		135.0m ²	
				860.3m ²		
				or 860.63m ²		
③	Repair to Pft holes mix seal shoulder					
cu	4	3.5	1.0		14.0m ²	
	10	9.0	1.05		97.50m ²	
	18	3.0	1.0		24.0	
	6	7.0	1.50		63.0m ²	
Continuation						
	2	5.5	1.25		13.75m ²	
					202.25	
					199.22m ²	

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) maintenance of Hume					
Pipe culvert					
map. 98	2 No	1104.34	each		22092
(6) maintenance of slab					
type of culvert					
map. 98	8 No	2287.21	each		18298
(7) maintenance of 200m/km					
stone Post					
map. 98	-	1.83	km		
		1067.44	km		1953
					209889
					(-) 20989
					188900

m³/m

1101124

cu
1101124

8 A.O

C.R.P

29/1/24

Continuation