

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, सिवान-1

पत्रांक 1992 (कृषि)

सिवान-1, दिनांक 31/7/24

प्रेषक :- कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, सिवान-1

सेवा में,
अपर-मुख्य-कार्यपालक पदाधिकाारी
ग्रामीण कार्य विभाग
विश्वेशरैया, पटना।

विषय :- MMGSY (SC & GEN) योजनान्तर्गत अनुरक्षण मद हेतु आवंटन उपलब्ध कराने के सम्बंध में।

महाशय,

उपर्युक्त विषय के सम्बंध में कहना है कि MMGSY(SC & GEN) योजना के लिए अनुरक्षण मद में राशि की आवश्यकता है।

अतः अनुरोध है, कि प्रधिकृत पत्र निर्गत करते हुये संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय, ताकि कराये गये कार्य का शीघ्र भुगतान किया जा सके।

अनु०- विहित प्रपत्र में मॉग विवरणी।

विश्वासभाजन

31/7/24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमण्डल,
सिवान-1

MIGSY New के लिए अनुसूचा मद् की राशि से संबंधित अधियावना प्रपत्र

कार्य परवस का नाम :- ग्रामीण कार्य विभाग कार्य परवस, सिवान-1															
क्रमांक	प्रपत्र का नाम	संबंधक का नाम	कार्य पूर्ण होने की वार्षिक तिथि	पूर्व में उपलब्ध कराये गए राशि का विवरण						वर्तमान अधियावित राशि					
				प्रथम वर्ष (लाख में)	द्वितीय वर्ष (लाख में)	तृतीय वर्ष (लाख में)	चतुर्थ वर्ष (लाख में)	प्रथम वर्ष (लाख में)	कुल (लाख में)	प्रथम वर्ष (लाख में)	द्वितीय वर्ष (लाख में)	तृतीय वर्ष (लाख में)	चतुर्थ वर्ष (लाख में)	प्रथम वर्ष (लाख में)	कुल (लाख में)
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
1	T01 to Rajampura Harjan Tola	COHESIVE INFRASTRUCTURE DEVELOPERS PRIVATE LIMITED	21.11.2017	0.000000	0.000000	0.00	0.00	0.00	0.000000	0.92571	1.20952	3.11416	4.01079	4.85456	14.11474
Total									0.000000						14.11474

RWD Works Division, Siwan-1

Executive Engineer
RWD Works
Division, Siwan-1

PIU:- E.E., R.W.D. Works Division, Siwan-1

2. Certified that I have satisfied myself that the conditions which the grants in aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money, was actually utilized for the purpose for which it was sanctioned.

- i Works have been supervised by Executive Engineer/Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

- i Construction of Road Works.
- ii Construction of CD Works.

Shaw
- 3117124
E.E.
RWD Works Division, Siwan-01