

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
WORK: Maint of Road from Chatgon Mohapar P.W.D Path to Katariya (Desiya) Tak					
Agency: Dinkar Kumar					
Agr. No.- 16 CBD/2021-22					
Date of start - 11.06.2021					
D.O. Completion - 10.12.2022					
A.D.O. Completion - 21.07.2022					
① Restoration of rain cuts with soil					
----- 7 x 5.40 x 1.125 x 0.300 - 12.76 m <sup>3</sup>					
5 x 7.25 x 1.05 x 0.250 - 9.52 m <sup>3</sup>					
4 x 9.60 x 1.125 x 0.300 - 12.96 m <sup>3</sup>					
6 x 6.20 x 1.10 x 0.200 - 8.18 m <sup>3</sup>					
5 x 4.70 x 1.125 x 0.400 - 10.57 m <sup>3</sup>					
6 x 4.25 x 1.05 x 0.350 - 7.65 m <sup>3</sup>					
3 x 11.20 x 1.05 x 0.300 - 10.58 m <sup>3</sup>					
2 x 18.00 x 1.125 x 0.300 - 12.15 m <sup>3</sup>					
7 x 4.00 x 1.05 x 0.280 - 7.18 m <sup>3</sup>					
4 x 3.75 x 1.125 x 0.300 - 5.06 m <sup>3</sup>					
					96.61 m <sup>3</sup>
CARRY forward					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Maintenance of CD work in HP culvert - - - - -					1. 60 NTS
⑤ Maintenance of Road signs - - - - -					0.31 km
⑥ Maintenance of road and km slope - - - - -					0.26 km
⑦ cutting of branches of trees - - - - -					4.00 NTS
⑧ Cutting of shrubs from road ways - - - - -					5 x 4 w - - - - - 20.00 NTI
⑨ Trimming of grass and Weeds - - - - -					5 x 10.0 x 0.100 - 5.0 m <sup>2</sup>
					3 x 7.00 x 0.100 - 2.10 m <sup>2</sup>
					2 x 8.50 x 0.180 - 1.70 m <sup>2</sup>
					8.70 m <sup>2</sup>

Continuation

10/08/23  
JB

1<sup>st</sup> year Maintenance

ABSTRACT OF COST

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of rain cuts with soil					
					- - - - -
					- - - - -
					- - - - -
Vm BP-46	Qty	96.61 m <sup>3</sup>			
	CR	404.56 / m <sup>3</sup>			39036/-
② Making up of Burrs/ shoulders					
					- - - - -
Vm BP-47	Qty	596.32 m <sup>2</sup>			
	CR	60.28 / m <sup>2</sup>			35946/-
③ Patch repair over potholes with 75 mm					
					- - - - -
					- - - - -
Vm BP-47	Qty	45.08 m <sup>2</sup>			
	CR	228.41 / m <sup>2</sup>			10297/-
④ Maintenance of C.D. work in HP Culvert					
					- - - - -
Vm BP-48	Qty	1.00 nos			
	CR	1166.58 / nos			1167/-
⑤ Maintenance of road signs					
					- - - - -
Vm BP-48	Qty	0.21 km			
	CR	1104.58 / km			235.00
⑥ Maintenance of zoom and KM stone					
					- - - - -
Vm BP-48	Qty	0.26 km			
	CR	583.43 / km			149/-

Continuation

86830/-

Sch. XLV-Form No. 134

## Materials

B/w - 161.90w

~~Stone -~~ 122 m<sup>3</sup>

Emulsion - 37-419

Bifurcata 51.4-1  
86.0 kg

Continuation

10/08/23