

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(i) Name of road -	Maintenance of road from				
Pooh To Bel Daniya Sajjanpur shakha	To chhoti Malauan.				
Agency -	Satyendra Kumar con. cons. Ltd.				
Nr. No -	42-SBD/2018-19				
Date of commencement -	28.11.2018				
Date of completion -	27.11.2019				
Actual date of completion -	26.11.2019				

Survey

D Restoration of rain cuts

.....
.....
56 X 0.60 X 1.20 X 0.30	12.0964 m^3			
.....	
52 X 0.75 X 1.20 X 0.30	14.0404 m^3			
54 X 0.90 X 1.20 X 0.30	17.4964 m^3			
48 X 1.25 X 1.20 X 0.30	21.6004 m^3			
44 X 1.45 X 1.20 X 0.30	22.9684 m^3			
40 X 1.75 X 1.20 X 0.30	25.2004 m^3			
36 X 1.90 X 1.20 X 0.30	24.6244 m^3			
32 X 2.25 X 1.20 X 0.30	25.9204 m^3			
28 X 2.65 X 1.20 X 0.30	26.7124 m^3			
34 X 2.45 X 1.20 X 0.30	29.9884 m^3			
26 X 2.85 X 1.20 X 0.30	26.6764 m^3			
18 X 3.15 X 1.20 X 0.30	20.4124 m^3			
6 X 3.60 X 1.20 X 0.30	7.7764 m^3			
4 X 4.15 X 1.20 X 0.30	5.9464 m^3			
				281.4844 m^3

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Maintenance of pathways, shoulders					
	2X	14X	3.40 X	1.20	114.24 m ²
	2X	8X	4.60 X	1.20	88.32 m ²
	2X	6X	6.90 X	1.20	99.36 m ²
	2X	12X	3.40 X	1.20	213.12 m ²
	2X	6X	9.60 X	1.20	138.24 m ²
	2X	3X	7.70 X	1.20	55.44 m ²
					708.72 m ²
⑤ Patch repair over pot holes					
	2X	12X	0.60 X	0.50	13.80 m ²
		34X	0.80 X	0.65	17.68 m ²
		12X	1.70 X	1.15	22.46 m ²
					73.84 m ²
⑥ Maintenance of drain					
	2X	12X	0.60 X	0.60	850.00 m ²
					850.00 m ²
⑦ Maintenance of H.P. culvert					
	2X	12X	0.60 X	0.60	9.00 m ²
					9.00 m ²
⑧ Heat maintenance of slab culvert					
	2X	12X	0.60 X	0.60	1.00 m ²
					1.00 m ²
⑨ Cutting of branches of trees					
	2X	12X	0.60 X	0.60	4.00 K.N.
					4.00 K.N.
Continuation					

Sect. XLY Form No. 124

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B.F.					16112.169200
(5) Maintenance of H.P. Cutwork					
9.00 Nos VTMSP-51	@ Rs 949.33 / No				Rs 8544.00
(6) Maintenance of Slab Cutwork					
1.00 No VTMSP-51	@ Rs 1976.62 / No				Rs 1977.00
(7) cutting of branches of Tree					
4.00 K.H. VTMSP-51	@ Rs 69.48 / K.H.				Rs 278.00
(8) white washing of Parapet walls					
57.85 m ² VTMSP-52	@ Rs 70.65 / m ²				Rs 4052.00
LESS 10% Deductions for agreement - Rs 1570.20 = 00					
<u>28 12 20</u>					Rs 14131.80
J.E.					

Continuation

and your Maintenance Bill

66

Seb. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road - Main road off Road from Post 78 Belgaon to Gajananpur Shekhara To Chhoti Malawati.					
Affexy - Sattgadha ka. f. Cow. corer. P.M. Corer.					
App No. 42- SBD/2018-19					
Actual date of completion - 26.11.2018					
<u>Stems</u>					
① Restoration of road cuts					
.....	20	1.20	0.30	0.10	
	52	\times 0.60	\times 1.20	\times 0.30	11.232 m ³
	48	\times 0.78	\times 1.20	\times 0.30	12.960 m ³
	46	\times 0.90	\times 1.20	\times 0.30	14.944 m ³
	42	\times 1.15	\times 0.20	\times 0.30	14.388 m ³

② Maintenance of External Shoulder

2X	14X	4.90×1.20	164.64	m^2
2X	12X	6.30×1.20	181.44	m^2
2X	10X	8.45×1.20	202.80	m^2
2X	8X	10.60×1.20	203.52	m^2
Continuation			752.40	m^2

Continuation

752.4041²

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
D.P.					153.1 cu m
	2x	4x	10.20x1.20		97.92 cu m
					250.32 cu m

③ Patch repair over Pot holes

				146.99542
	56x	0.60x	0.50	16.80442
	52x	0.75x	0.60	23.40442
	48x	0.90x	0.75	32.40442
	42x	0.90x	0.90	34.02442
	26x	1.25x	0.95	40.37542
				146.99542

④ Maintenance of skin

• - - - - - 20 - - - - - 20 - - - - - 61

⑤ Maintenance of Hif culture

	9.00 Nos.	9.00 Nos

⑥ Maintenance of Slab type culvert

E) Maintenance of Road signs

-----80-----80-----e₁₂

Maintenance of K.M. f. H. stone

	σ_{00}	σ_{01}
	4.00 KN.	4.00 KN.

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Cutting of branches of trees					

② White washing on Parapet walls					

③ Laying of tiles					

④ Restoration of earth cuts					

⑤ Maintenance of earthen shoulder					

⑥ Patch repair over Pot holes					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	B.P.				Rs 135394/-00
(4) Maintenance of Drains					
	20	20	612		
	850.00m	VTMOP-56			
	@ Rs 2.10/m				Rs 1786200
(5) Maintenance of H.P. culvert					
	80	80	842		
	9.00 Nos	VTMOP-56			
	@ Rs 944.33/Nos				Rs 8544200
(6) Maintenance of Slab type culvert					
	20	20	612		
	1.00 Nos.	VTMOP-56			
(7) Maintenance of Road signs					
	20	20	612		
	4.00K.M.	VTMOP-56			
	@ Rs 935.03/K.M.				Rs 3740200
(8) Maintenance of K.N & M. Stone					
	20	20	612		
	4.00K.M.	VTMOP-56			
	@ Rs 622.71/K.M.				Rs 2511200
(9) Cutting of branches of trees					
	20	20	612		
	4.00K.M.	VTMOP-56			
	@ Rs 69.48/K.M.				Rs 278200
					Rs 15423320

Continuation

Sch. XLV-Form No. 134

66

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B.P.					Rs 154233.00
(D) White washing of Parapet walls					
54.85sqft VTM B.P - 54					
@ Rs 70.05sqft					Rs 4052.00
NET TOTAL					Rs 158285.00
Gross 10% Below as per Agreement - Rs					158292.00
Copy 1112					Rs 142456.00
NET TOTAL					
Gross 10% Below as per Agreement - Rs					
158292.00					

Material statement

Continuation