

2nd Year Maintenance

Sch. XLV—Form No. 134

37

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/nm. Maint. of Road from Kairigawan to Kairi Bala (A Nankar) under MMTG&H.					
Agency - M/s New Bharat Coast. Company -					
Aj. No - 98SRD/MMG&H/2021-2022					
Date of Start - 14/07/2021					
Actual completion - 17/06/2022					

Pecard Gandy

① Restoration of rain

cufs ← 0 ←

$$6 \times 4.50 \times 1.49 \times 0.39 = 11.34$$

$$8 \times 4.10 \times 1.50 \times 0.30 = 14.76$$

$$7 \times 3.60 \times 1.30 \times 0.30 = 9.85$$

$$9 \times 4.00 \times 1.30 \times 0.30 = 14.04$$

$$6 \times 5.10 \times 1.20 \times 0.30 = 11.88$$

$$9 \times 4.00 \times 1.25 \times 0.30 = 13.50$$

$$8 \times 3.40 \times 1.45 \times 0.30 = 11.83$$

$$3 \times 3.80 \times 1.90 \times 0.30 = 4.45$$

90-77

$$90.77 \text{ m}^3$$

② Mainly of Earth.

Shoulder — do —

$$2 \times 8 \times 30.00 \times 0.90 = 480.00$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

$$20 \times 8.5 \times 0.80 = 86.00$$

$$1682.00 \text{ m}^2$$

⑨ while working of road

formed width — 0 —

$$10 \times 2 \times 8.75 \times 0.85 = 63.00 \text{ m}^2$$

⑩ Maint. of Road by

Pondalde — 0 — 150.00 Nos

Ajanta

15/06/94
-.-

Abstract of cost

① Restoration of rain

rds. — 0 —

90.77 m³ — wide — P-37

cr. 407.70/m³. — — — 6 32007.00

② Maint. of Gutter

shoulder. — 0 —

504.54 m² — wide — P-37

cr. 60.79/m² — — — 6 30672.00

