

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st year maintenance.</u>					
N/W.					
Agreement No - 0	55. B.D / 21-22				
Agency - Surendra Kumar Singh					
Date of Work order	03/09/21				
Date of completion Actual	17/4/23				
Date of entry	09/04/21	18/5/21			
(a) Restoration of rain water with soil					
	2x4+9.50x1.00x.25				50 m ³
					Limit 47.58 m ²
(b) making up Berms/shoulder stripping excess soil the shoulder					
	2x4x2.50x1.00				200 m ²
	2x10x2.00x1.00				400 m ²
	3x10x2.00x1.00				600 m ²
					Limit 490.25 m ²
(c) Patch repair over B.T turning surface with 20 mm Poemix					
	1	8.00	1.80	—	9.6 m ²
	2	4	1.90	—	7.9 m ²
	1	6.00	1.80	—	4.8 m ²
	1	11	1.85	—	9.3 m ²
	1	4	1.10	—	4.4 m ²
Beliondale	1	2	1.60	—	1.2 m ²
Continuation					
					36.5 m ²

Sch. XLV-Form No.134

Sch. XLV-Form No.134 47

Continuation

Sch. XLV-Form No.134 48

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
Abstraction of costs						
(a) Restoration of road cuts						
					Washed	
	47.58 m ³	Gumdale P.m.B	P 46			
	at 379.59 /m ³		R 18061/-			
(b) making up Berms, shoulder						
					striking off less earth	
					from the shoulder	
	490.95 m ²	Gumdale P.m.B	P 46			
	at 57.01 /m ²		R 27949/-			
(3) Patch repair over Bitumen						
					surface with 20 mm trench	
					carried with seal 20 at Zehr B.	
	32.5 m ²	Gumdale P.m.B	P 46			
	at 280.26 /m ²		R 10229/-			
(4) maintenance of C. & work						
					Gumdale P.m.B P 47	
					at 1102.81 /Mn	
					R 22062/-	
(5) maint of road grass						
					1.98 km Gumdale P.m.B P 47	
					at 1054.28 /km	
					R 10332/-	
(6) maint of 222 m of 7cm stone						
					1.29 km Gumdale P.m.B P 47	
					at 688.17 /km	
					R 8022/-	
(7) white washing of Parapet wall						
					14.12 m ² Gumdale P.m.B P 47	
					at 816.40 /m ²	
					R 2322/-	
					Continuation	
					59912/-	

Continuation