

મુદતપૂર્વે આપસપર્ય પોતાનામાંથી રાનીગણપ્રસંગ  
- 10 થી 20 થી દોષાગ્ર આપણી દોષાગ્ર આપણી  
નિર્મિત સ્વયંની વર્ષો ગ્રહ - 22 થી 20 થી

**Schedule XLV-Form No 134**  
સુધાર સમાપ્ત કરેલ - 15/6/2018

સુધાર સમાપ્ત કરેલ - 15/6/2018

**DIVISION**

સુધાર સમાપ્ત કરેલ - 15/6/2018

સુધાર સમાપ્ત કરેલ - 15/6/2018

**SUB-DIVISION**

સુધાર સમાપ્ત કરેલ - 15/6/2018

(ST)

**Measurement Book**

સુધાર સમાપ્ત કરેલ - 15/6/2018

# 2<sup>nd</sup> Year Maintenance Bill

44

Sch. XLV-Form No. 134

| Particulars                  | Details of actual measurement |    |    |            | Contents of area |
|------------------------------|-------------------------------|----|----|------------|------------------|
|                              | No.                           | L. | B. | D.         |                  |
| N/B: Maintenance of Road     |                               |    |    |            |                  |
| from 10 no. Senthallala      |                               |    |    |            |                  |
| to Shastri Tola              |                               |    |    |            |                  |
| under MATHS                  |                               |    |    |            |                  |
| Agency: Ashok Kumar          |                               |    |    |            |                  |
| Ag. NO: 86 SBD/2017-18       |                               |    |    |            |                  |
| Date of Start: 17-02-18      |                               |    |    |            |                  |
| Date of Completion: 16-02-19 |                               |    |    |            |                  |
| Actual Date of Completion: - |                               |    |    |            |                  |
|                              |                               |    |    | 19-11-2018 |                  |
| Date of Entry: 28-1-2019     |                               |    |    |            |                  |

|                                                |  |  |  |  |  |
|------------------------------------------------|--|--|--|--|--|
| 1) Restoration of Rain cut                     |  |  |  |  |  |
| with Soil - - -                                |  |  |  |  |  |
| 2 x 9.0 x 1.20 x 0.60 = 12.96 m <sup>3</sup>   |  |  |  |  |  |
| 4 x 11.0 x 1.30 x 0.55 = 31.46 m <sup>3</sup>  |  |  |  |  |  |
| 1 x 26.90 x 1.10 x 0.80 = 23.67 m <sup>3</sup> |  |  |  |  |  |
| 2 x 16.90 x 1.25 x 0.40 = 16.90 m <sup>3</sup> |  |  |  |  |  |
| 2 x 22.0 x 1.20 x 0.90 = 47.52 m <sup>3</sup>  |  |  |  |  |  |
| 3 x 12.0 x 1.30 x 0.65 = 30.42 m <sup>3</sup>  |  |  |  |  |  |
| 1 x 29.40 x 1.20 x 0.75 = 26.46 m <sup>3</sup> |  |  |  |  |  |
| 6 x 8.0 x 1.15 x 0.80 = 44.16 m <sup>3</sup>   |  |  |  |  |  |
| 1 x 23.40 x 1.25 x 0.70 = 20.48 m <sup>3</sup> |  |  |  |  |  |
| Total: 254.03 m <sup>3</sup>                   |  |  |  |  |  |

Continuation

## Sch. XLV-Form No. 134

| Particulars                                          | Details of actual measurement |    |    |    | Contents of area              |
|------------------------------------------------------|-------------------------------|----|----|----|-------------------------------|
|                                                      | No.                           | L. | B. | D. |                               |
| (4) Maintenance of stone type culvert - - -          |                               |    |    |    |                               |
|                                                      |                               |    |    |    | - 1 Nos.                      |
| (5) Maintenance of Road signs - - -                  |                               |    |    |    |                               |
|                                                      |                               |    |    |    | - 2.510 km                    |
| (6) Maintenance of 200m and 15m stone - - -          |                               |    |    |    |                               |
|                                                      |                               |    |    |    | 0.420 km                      |
|                                                      |                               |    |    |    | - 0.326 km                    |
| (7) 1/2 hit. washing two coats on parapet wall - - - |                               |    |    |    |                               |
|                                                      |                               |    |    |    | 2 x 4 x 6 = 48 m <sup>2</sup> |

As per surface condition limit - 42.05 m<sup>2</sup>  
 surface is good

At present Road surface is good condition  
 CLS

02/2/23  
 AR

As per present road condition, surface is good.

95 ~~Answer~~  
28-1-23

572

Material statement

|                |          |
|----------------|----------|
| Earthwork (ft) | 402.15 m |
| Bitumin Sgo    | 233.51 m |
| Stone chips    | 2.95 m   |

ans

19/11/2019

25

45

042112  
186