

5th year maintenance

57

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w - const at road from Loer to Chandanpur Agency - Sri Navin Kumar Agg. No - SBD/3/2017-18					
Actual Date of Comp - 10.10.2018 Date of Entry - 09.12.2017					
151CA) Restoration of rain cut - do - self					
2X27X50m X 1.125m X 0.300m = 91.125m ³					
2 15.2ED) making up loss of material do - self comp 25X40m X 2.25m = 50X25m					
3 15.9) maintenance of road sign - do - self Qty = 1.001cm					
4 15.74) maintenance of H-P culvert - do - self Qty = 1 Nos					
5 15.74) maintenance of slab culvert - do - self Qty = 2 Nos					

Continuation

[illegible]