

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year Maintenance					
on A.P. P.S.U.					
① Name of worker-					
Maintenance of road					
from Milleri Sirsihame					
path to Mahammad					
Pur Dalwa wa Ganga					
brgha					
② Name of Agency-					
Sri Sanjay Kumar					
③ Agreement No-					
215				74/800/18-19	
④					

① Restoration of rain					
Cuts/benches with soil					
etc. all completely.					
5x 5.60 x 1.10 x 0.30					9.24
5x 5.50 x 1.05 x 0.30					8.66
5x 7.25 x 1.10 x 0.30					11.94
8x 8.40 x 1.10 x 0.30					21.12
4x 9.50 x 1.10 x 0.30					12.54
6x 8.75 x 1.10 x 0.30					17.32
4x 9.25 x 1.10 x 0.30					11.88

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
6x8-70x1.10x0.30=					17.22
					Ans-109.94m
					Ans-109.35m
② Making up of beams					
Shoulders etc.					all
Complete					
6x11.00x1.10=					66.00
4x14.25x1.10=					59.12
8x12.50x1.10=					110.00
7x10.50x1.10=					73.50
5x13.00x1.10=					65.00
2x10.00x1.10=					22.00
5x12.50x1.10=					62.50
6x10.00x1.10=					66.00
7x14.50x1.10=					101.50
					Ans-607.50
③ Repair of Pot					
holes etc.					all
Complete					
2x5.00x1.25x0.08=					0.99
2x10.00x1.25x0.08=					1.96
3x8.50x1.50x0.08=					2.84
2x12.50x1.25x0.08=					3.20
					Ans-9.09m
④ Patch repair over					
Pot holes mix seal					
Surface etc.					all

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Cement plaster					
2x 5.50 x 1.70	2				11.70
2x 10.50 x 1.25	2				26.25
3x 8.50 x 1.50	3				38.25
2x 12.50 x 1.75	2				43.75
2x 2.70 x 1.80	2				9.72
					128.87
					128.91
(5) Manut. of G.O. work					
H.P. Culvert etc.					
all completers					
Qty. 3 nos.					
(6) Cutting of branches					
of trees etc. all					
completers					
Qty. 3 nos.					
(7) Cutting of shrubs					
from road way etc.					
all completers					
Qty. 11 nos.					
(8) White washing of					
Parapet walls etc.					
all completers					
4x 7.70 x 1.20	4				30.84
4x 0.80 x 0.80	4				16.64
2x 7.70 x 0.40	2				6.16

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
	4 x 6	40 x	0.60 =		15.36 m ²
	4 x 0.80	x	0.60 =		1.92 m ²
	2 x 8	80 x	0.40 =		7.04 m ²
					Total 62.88 m ²
					Total Area

ABSTRACT OF COST

① Restoration of crown cuts etc. all complete

153

Its same. As not

Dr. B. P. 77

Oct 109 30 MB

② $FB = 362.23$ mR 39.609

② making up of

berms / shoulders

etc. all completers

Al ₂	same	fr	val
-----------------	------	----	-----

Time = 10.77

607.57 M²

Continuation C. 0 F 39609-

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
					B. P B 99,602
					Qty 607.50m ²
					Qty 53.70/m ² B 32,625
③ Repair of pot holes etc. all comp					
complete					
					Qty 1000m ²
					Qty 9,000m ³
					Qty 9525.56/m ² B 86,587
④ Patch repair over pot holes mix surf					
surface etc - all					
complete					
					Qty 1000m ²
					78
					Qty 128.91m ²
					Qty 199.60/m ² B 5,730
⑤ Maint. of C.D					
work H. P. Culvert etc.					
all complete					
					Qty 1000m ²
					Qty 3m ²
					Qty 1122.29/m ² B 3366
⑥ Cutting of branches of trees etc. all					
complete					

Continuation C.O.B 1,87,91

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B. 187.917		
Qty. Same as vide					
TMW 1-10-80.					
Qty. 3110.					
@ 106.55/cum					3192
⑦ Cutting of shrubs					
from road etc.					
all complete work.					
Qty vide TMW 28					
Qty 11110					
@ 136.55/cum					722
⑧ white washing					
of parapet wall					
etc. all complete work					
Qty vide TMW 28					
Qty 6288 m ²					
@ Rs 16.33/m ²					10280
					Total Rs 189.3
⑨ below 1.37% B					259
					Total Rs 1,86,70
clg Himanshu 30-07-24 EE					AE

Scanned with OKEN Scanner