

સુરેશ કેશવ રામકૃષ્ણ

(SC)

Shedule XLV Form No. 134.

F.E. R. 11.10. (W)

DIVISION
515/17

A.F. R. 11.10. (W)

SUB-DIVISION
WA212 519NS

Measurement Book

Page 1d - PT 333668

2935

1.
Name of work -
Situation of work -
Agency by which work is executed -
Date of measurement -
No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ist on A/c Bill					
Name of work - Const of rural road					
from - Itan Tolg Simstipur					
to - To 6 ODR under MMCSY					
Agency: Satyendra Yadav					
Agst no: 56/MMCSY/SC/SBD/202021					
Drawn: 15-09-2020					
TOC: 14-09-2021					
Date of Measurement: 1-3-2021					

① Const of ref & working
BM level detail
1.402 Km

② Cleaning & grubbing
of road land detail

$$20 \times 30.00 \times 6.50 = 3900.00 \text{ m}^2$$

$$20 \times 30.00 \times 7.00 = 4200.00 \text{ m}^2$$

$$6 \times 30.00 \times 6.00 = 1080.00 \text{ m}^2$$

$$17 \times 22.00 \times 6.00 = 1320.00 \text{ m}^2$$

$$9312.00 \text{ m}^2$$

$$\text{or } 0.921 \text{ Hect}$$

③ Const of embankment with
material obtained from
borrow pit detail

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Const. of rural road from					
Itwa Tola Samastipur to TOG					
ODR - under M.H.G.S. (SC)					
Agency - Satyendra Yadav					
Agg. No - 56/M.H.G.S./SC/CLD/20-21					
DOW - 15.09.20					
ADC - 17.04.83					
(1) Restoration of main cuts					
59.3343					
(2) Making up of Broom's/					
Shoulder.					
329.6342					
(3) Repair of pot hole					
0.0843					
(4) Patch repair over					
potholes					
27.4742					
(5) Patch repair over					
Bituminous.					
27.4742					
(6) Filling of cracks and					
Joint.					
1172.004					
(7) Repair of isolated					
area of damaged.					
5.2942					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
		Abstract of cost				
(1)	Restoration of rain cut.					
P/47		59.33 y ³				
		@ 404 = 06		b = 23978 = 00		
(2)	Making up of Booms					
P/47		339.63 y ²				
		@ 60 = 28		b = 19870 = 00		
(3)	Repair of Pot hole					
P/47		0.68 y ³				
		@ 92 90 = 04		b = 743 = 00		
(4)	patch repair over potholes.					
P/47		27.47 y ²				
		@ 243 = 28		b = 6683 = 00		
(5)	patch repair over Bituminous.					
P/47		27.47 y ²				
		@ 260 = 70		b = 7161 = 00		
(6)	Filling of cracks and joints.					
P/47		1172.00 y ⁴				
		@ 3 = 85		b = 4512 = 00		
(7)	Repair of isloane-p.					
P/47		539 y ²				
		@ 243 = 28		b = 1311 = 00		

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8)					
Maintenance of					
C/D work					
P/47		4.00 NO			
		@ 1166=58			l= 4666=00
(9)					
Maintenance of C/D					
work.					
P/48		1.00 NO			
		@ 2394=96			l= 2395=00
(10)					
Maint of road side					
P/48		1.40 km			
		@ 1104=59			l= 1546=00
(11)					
Maint of 200m x 10m					
stone.					
P/48		1.40 km			
		@ 642=17			l= 900=00
(12)					
Cutting of boundary					
of road.					
P/48		3.00 NO			
		@ 113=64			l= 341=00
(13)					
Cutting of shrubs					
P/48		1173.00 NO			
		@ 6=98			l= 8181=00
(14)					
Trimming of trees					
and weeds.					
P/48		2624.00 NO			
		@ 2=33			l= 6144=00

Continuation

11/10/2024
 20/04/24
 JE

12/10/2024
 20/07/24
 AE

Material Statement

(1) F/W - 59.3343
 (2) S/clips - 0.74193
 (3) Pitterman - 0.05247

11/10/2024
 20/04/24
 JE

Continuation

Continuation