

MEASUREMENT BOOK

27/11/2022 -

SAN THOULA
SUB DIVISION

M.M.C.S.V. ROAD
DIVISION

KHARRARA SANTHAL PARAGANA CHANDPUR

CHADPUR HOUSE OF SIVARAMMANDAL
TO

302

Schedule XLV From N 134

G.I.S.N.Y.



CamScanner

Particulars	Details of actual measurement			
	No	L	B	D

Sanctioned Maintenance

Name of work: Chandpur house
of S. Varan extended to Kharabha

Sanctioned portion Chandpur

MHWSY Road (Under 177.5m) set

by/A: S. Varan Kharabha

Agreement No: SB2/16/2018-2019

Date of Work done: 20-7-2018

Actual order of Comp: - 2-1-2019

Date of Entry

① Restoration of rainfed

within Soil moisture

8 x 5.0m (1.00 ± 0.80) = 8.00 10.80

6 x 4.0m (1.00 ± 0.85) = 0.20 = 4.00

2

5 x 6.0m (1.00 ± 0.80) = 0.15 = 4.05

2

Total = 19.29m

② Maintenance of Earthen

Shoulder

10 x 6.0m (1.00 ± 0.80) = 6.00m

5 x 4.0m (1.00 ± 0.80) = 1.80m

6 x 3.0m (1.00 ± 0.80) = 1.40m

3 x 5.0m (1.00 ± 0.80) = 1.50m

Total = 10.70m

③ Maintenance of Road side

(Continuation)

[illegible]