

Papua Koro
Dymuln Ilre Road To Kolhore,
Shedule XLV Form No. 134.

E. E. R. W. D. (W)

DIVISION
GAYA

A. E. R. W. D. (W)

SUB-DIVISION
BODH GAYA

Measurment Book

2808

(Gen)

Pay

Particulars	Details of actual measurement				Contents of area
	No.	L,	B,	D,	
Name of Work - Road work maint of road from Dargah to Ilaq Chakki road totalling under MHSY.					
Agency - Pappukural					
Estt NO- 28/SOP/MHSY/2019-20					
AEC - 2.05.20					
(1) Restoration of main cut					
(2) Making up of Beemal shoulder					
(3) Repair of pot hole					
(4) Patch repair over Pot holes.					
(5) Patch repair over Bituminous					
(6) Filling of cracks and Joint.					

Continuation

Sch. XIV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
(9) Main of road by road				
P/45		0.3 1/2 km		
	@	1074 = 51	b =	419 = 00
(10) cutting of boundary				
P/45		0.3 9 km		
	@	643 = 75	b =	251 = 00
(11) cutting of boundary of trees.				
P/45		3.00 NO		
	@	106 = 52	b =	390 = 00
(12) cutting of shrubs				
P/45		28.5.0042		
	@	6 = 53	b =	2518 = 00
(13) Trimming of grass and weeds				
P/45		867.0042		
	@	2 = 18	b =	1890 = 00
(14) white washing of boundary				
P/45		42.0042		
	@	16 = 21	b =	681 = 00
			b =	1119 00 = 00
			b =	134 98 = 00
			b =	1119 = 00
			b =	126 447 = 00
			b =	126 44 = 00
			b =	113 803 = 00

Continuation

4th Year Maintenance

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - 4th Year Maint of road from Daman Khan Targ chak road to Kollang under highway					
Agency - Pappu Kumar					
Agg No - 28/2014 MHSY/ 2019-20					
ADC - 2.05.20					
(1) Restoration of road cut					
		31.1	9.43		
(2) Making up of Road					
		173.25	4.2		
(3) Repair of Pot holes					
		0.11			
(4) Patch repair over Pot holes					
		36.09	4.2		
(5) Patch repair over Bituminous					
		36.09	4.2		
(6) Filling of cracks and Joint					
		385.00	4		
(7) Maint of old works					
		2.00	NO		
(8) Maint of road sign					
		0.3	7 km		
(9) Maint of road km					
		0.39	km		

Continuation

81
Sd/- XIV-Form No. 184

Particulars	Details of actual measurement				Contents of area
	No.	L ₁	B ₁	D ₁	
		Thickness of Cast			
(1)	Reinforcement of beam				
	Cub				
P/49		31.743			
		Q 380 = 58		b = 11846 = 00	
(2)	Making up of beams				
P/49		1.73.2542			
		Q 58 = 37		b = 10113 = 00	
(3)	Repair of Pot Lohay				
P/49		0.1142			
		Q 10561 = 16		b = 1162 = 00	
(4)	Patch repair over Pot Lohay.				
P/49		36.0942			
		Q 295 = 25		b = 10656 = 00	
(5)	Patch repair over bituminous.				
P/49		36.0942			
		Q 299 = 39		b = 10805 = 00	
(6)	Filling of cracks and Joint.				
P/49		385.004			
		Q 4 = 69		b = 1806 = 00	
(7)	Maint of c/d Noisy				
P/49		2.0040			
		Q 1117 = 00		b = 2294 = 00	

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8)	Maint of road				
	Sign				
P/49		0.39 km			
		@ 1074 = 51		b =	419 = 00
(9)	Maint of 200mm ² con				
P/49		0.39 km			
		@ 643 = 75		b =	251 = 00
(10)	Cutting of boundary				
	of road				
P/49		3.00 No			
		@ 106 = 52		b =	320 = 00
(11)	Cutting of boundary				
P/50		385.00 No			
		@ 6 = 54		b =	2513 = 00
(12)	Trimming of roads				
	and roads				
P/50		867.00 m ²			
		@ 2 = 18		b =	1890 = 00
(13)	White washing of				
	boundary				
P/50		42.00 m ²			
		@ 16 = 21		b =	681 = 00
				b =	54 725 = 00
Add 12 % W.S.T				b =	65 67 = 00
Add 1 % W.S.T				b =	54 7 = 00
				b =	618 39 = 00
Below 10% (-)				b =	618 4 = 00
Continuation					
				b =	55655 = 00

1/1000
12/1/24
52

And
12/1/24