

4th year Maint



94

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :- Lalse Bhadaul					
Road to Kariachak via Dhangh					
Pur Narayanpur					
Name of Agency :- M/s Devendra					
Prasad					
Agreement no 25 SAD 2018/19					
Actual dt of completion 27.4.19					
① Restoration of drain cut					
3 NO X 5.5mx.90mx.30					=4.45m ³
5 NO X 6.5mx.80mx.30m					=7.8 m ³
6 NO X 7.5mx.70mx.30m					9.45m ³
7 NO X 8.5mx.80mx.30					14.28m ³
3 NO X 5.10mx.50x.30					= 2.29m ³
4 NO X 6.2mx.40x.25					= 2.48m ³
5 NO X 5.05mx.80 X.30m					6m ³
10 NO X 2.5mx.65mx.30					= 4.87m ³
6 NO X 3.96mx.55x.30					= 3.92m ³
12 NO X 4.96mx.68x.30					= 12.14m ³
10 NO X 3.90mx.70x.30					= 8.19m ³
7 NO X 3.5mx.70x.30					5.14m ³
8 NO X 4.05x.50x.80					4.86m ³
5 NO X 1.60mx.60x.30					= 1.44m ³
10 NO X 2.5mx.70x.30					5.25m ³
3 NO X 5.10mx.50x.30					= 2.29m ³
Total					94.85m ³


Continuation


Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑨ Cutting of Shrub					
11 NO @ 41 TMM P-97					
11 NO @ 6.42/NO = 71					
⑩ Trimming of Potal					
5.8 m ² @ 41 TMM P-97					
5.8 m ² @ 2.19/m ²					= 12 = 0
Total					99572
Less 0.257 below 249 =					
Total					99323
 10.6.2023 JE  10/06/23 AE					

material statement

a) earth	—	152 m ³
b) stone chips	—	5.022 m ³
c) Bitumen	—	0.44 m ³
d) Base	—	10 NO
e) Coarse sand	—	0.30 m ³


10.6.2023
JE


10/06/23
AE