

Arvind ke Singh

M.M.G.SY अजीत खर्ग रत शिवमग

Schedule XLV-Form No. 134

E. E. R. W. D. (W)

DIVISION G.A.Y.A

A. E. R. W. D. (W)

SUB-DIVISION

BODHGAHA

Measurement Book

9826

Payee id - PT 523706



Name to work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ist on A/c B2/L					
Name of work: Const of road from					
Bagchi Khurd To Gopalpur					
under MMGSY					
Agency: Ashwin Kumar Singh					
Agst No: 26/SBD/MMGSY/Gen/2019-20					
Row: 3.8.2019					
Loc: 2.5.2020					
Date of measurement: 10.4.2020					
① Const of BM & road					
working for road					
0.658 km					
② Closing & grubbing					
of road land level					
$10 \times 30.00 \times 6.00 = 1800.00 \text{ m}^2$					
$10 \times 30.00 \times 6.50 = 1950.00 \text{ m}^2$					
$1 \times 30.00 \times 6.50 = 195.00$					
$1 \times 28.00 \times 6.50 = 182.00$					
					4127.00 m ²
					or 0.412 Hect
③ Const of embankment					
material obtained					
from borrow pit do do					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work—	4th Year Maint of gravel				
	road from Bagaliki to				
	Gopalpur under Munsy.				
Ag. H. No—	261500/Munsy/hem/2019-20				
Do W—	3.08.19				
To C—	2.05.20				
(1)	Restoration of rain cut.				
	2x	15.00x	1.20x	0.30	= 10.80 m ³
	2x	15.00x	1.20x	0.30	= 10.80 m ³
	1x	3.00x	1.20x	0.30	= 2.16 m ³
	2x	1.00x	1.20x	0.30	= 0.72 m ³
					24.48 m ³
(2)	Making up bad road				
	Shoulder.				
	2x	15.00x	1.00		= 30.00 m ²
	4x	15.00x	1.00		= 60.00 m ²
	2x	15.00x	1.00		= 30.00 m ²
	2x	8.00x	1.00		= 16.00 m ²
					136.00 m ²
(3)	Patch repair over				
	pot holes.				
	4x	7.00x	1.00		= 28.00 m ²
	1x	0.41x	1.00		= 0.41 m ²
					28.41 m ²
(4)	Patch repair over				
	bituminous.				
	4x	7.00x	1.00		= 28.00 m ²
	1x	0.41x	1.00		= 0.41 m ²
					28.41 m ²
Continuation					
	1x	0.41x	1.00		= 0.41 m ²
					28.41 m ²

Continuation

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
		Abstract of Cost				
(1/1)	Restoration of main					
	Culv.					
P/53		24.484 ³				
		@ 380 = 58			k = 9317 = 00	
(2/2)	Making up of Beams					
P/53		136.004 ²				
		@ 58 = 37			k = 7938 = 00	
(3/3)	Patch repair over					
	Pot holes.					
P/53		22.414 ²				
		@ 293 = 82			k = 8347 = 00	
(4/4)	Patch repair over					
	Bituminous.					
P/53		22.414 ²				
		@ 297 = 96			k = 8465 = 00	
(5/5)	Crack sealing-filling					
	of cracks and repair					
P/54		303.004				
		4 = 69			k = 1421 = 00	
(6/6)	Repair of isolated					
	area of damage sl.					
P/54		33.254 ²				
		@ 293 = 82			k = 9778 = 00	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(7/7) Removal of existing soulent and regally.					
P/54		332.824			
	@	23 = 45		b = 7805 = 00	
(8/8) Maint of c.p. work					
P/54		2.0000			
	@	1117 = 00		b = 2234 = 00	
(9/9) Maint of road S'gn.					
P/54		0.6600			
	@	1674 = 51		b = 709 = 00	
(10/10) Maint of room and con. stroy.					
P/54		0.6600			
	@	643 = 75		b = 425 = 00	
(11/11) cutting of branches					
P/54		4.0000			
	@	106 = 52		b = 426 = 00	
(12/12) cutting of shrub from road way.					
P/54		632.0000			
	@	2 = 18		b = 1484 = 00	
(13/13) White washing of parquet.					
P/54		42.0000			
	@	16 = 21		b = 681 = 00	
				b = 5903.3 = 00	
Below 10% (-)				b = 5903 = 00	
(11/11) JE				b = 53130 = 00	

Continuation