

| Particulars                         | Details of actual measurement |    |    |    | Contents of area |
|-------------------------------------|-------------------------------|----|----|----|------------------|
|                                     | No.                           | L. | B. | D. |                  |
| Name of Work : Maintenance of Road  |                               |    |    |    |                  |
| Particulars : Total to Total        |                               |    |    |    |                  |
| Under : GTS                         |                               |    |    |    |                  |
| Block : Kalyanpur                   |                               |    |    |    |                  |
| Agency : Shendilga Enterprise       |                               |    |    |    |                  |
| Gyatri Nager, Mother,               |                               |    |    |    |                  |
| E. Chauran,                         |                               |    |    |    |                  |
| Approval No : 23 SBD/2017-18        |                               |    |    |    |                  |
| Actual Date of comp : 07.06.2018    |                               |    |    |    |                  |
| Main work has been done by Agency - |                               |    |    |    |                  |

|                           |  |  |  |         |  |
|---------------------------|--|--|--|---------|--|
| 1. Restoration of Rain    |  |  |  |         |  |
| cut with soil             |  |  |  |         |  |
| 2x 6x 4.30x 0.60x 0.30 =  |  |  |  | 9.28    |  |
| 2x 10x 3.90x 0.50x 0.30 = |  |  |  | 11.70   |  |
| 2x 15x 3.25x 0.65x 0.30 = |  |  |  | 19.01   |  |
| 2x 8x 5.05x 0.70x 0.30 =  |  |  |  | 16.96   |  |
| 2x 13x 2.81x 0.45x 0.30 = |  |  |  | 9.86    |  |
|                           |  |  |  | T 66.81 |  |
| 2. Filling of Earthen     |  |  |  |         |  |
| Shoulder Filling          |  |  |  |         |  |
| 2x 4x 6.40x 0.65 =        |  |  |  | 33.28   |  |
| 2x 6x 5.60x 0.60 =        |  |  |  | 40.32   |  |
| 2x 8x 4.80x 0.55 =        |  |  |  | 42.24   |  |
| 2x 10x 4.00x 0.50 =       |  |  |  | 40.00   |  |

Continuation

| Particulars         | Details of actual measurement |    |    |    | Contents of area |
|---------------------|-------------------------------|----|----|----|------------------|
|                     | No.                           | L. | B. | D. |                  |
| 2. 5 x 7.20 x 0.70  |                               |    |    |    | = 50.40          |
| 2. 7 x 6.80 x 0.60  |                               |    |    |    | = 57.12          |
| 2. 9 x 6.00 x 0.65  |                               |    |    |    | = 70.20          |
| 2. 12 x 3.48 x 0.45 |                               |    |    |    | = 37.58          |
|                     |                               |    |    |    | 7 371.1642       |
| Abstract of cost.   |                               |    |    |    |                  |

|                      |                        |  |  |           |
|----------------------|------------------------|--|--|-----------|
| V <sub>1</sub>       | Restoration of drain   |  |  |           |
|                      | cuts with soil         |  |  | —         |
|                      | P. 42                  |  |  |           |
| 66.817 <sup>3</sup>  | 20 2 357.11            |  |  | 2 23458.1 |
| 2/2                  | Maintenance of earthen |  |  |           |
|                      | drain                  |  |  | —         |
|                      | P. 43                  |  |  |           |
| 371.147 <sup>2</sup> | 20 2 53.11             |  |  | 2 19711.1 |
|                      |                        |  |  | 1         |
|                      |                        |  |  | 2 43169.1 |
| less                 | 0.5% below             |  |  | 2 216.0   |
|                      |                        |  |  | 2 42953.1 |

Continuation