

2nd year maintenance

Sch. XLV-Form No. 134 36

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

N/w: Maint of Road from Logo

Dhobgama (Urban) to the RFO

Road Raitole chowk to

Agency. Rishiketh Rongon

Apr No. 19 (SBS) / 2020-21

Do. W.

Actual D.O.C. 30.04.2021

Date of entry.

① Restoration of RainCuts -

10 x 2.50 x 0.85 x 0.35 = 7.44

8 x 3.10 x 0.70 x 0.35 = 6.07

15 x 2.25 x 0.90 x 0.20 = 9.11

11 x 2.70 x 0.80 x 0.35 = 8.32

16 x 2.65 x 0.90 x 0.30 = 11.45

6 x 2.55 x 0.80 x 0.35 = 4.28

46.67 m³

② Making up of Berms -

6 x 5.10 x 0.85 = 25.60

15 x 4.10 x 0.80 = 48.60

10 x 6.10 x 0.85 = 51.60

12 x 5.10 x 0.75 = 45.60

15 x 7.10 x 0.80 = 84.60

253.50 m²

③ Patch repair with 20 mm

premix Surfacing

4 x 2.10 x 1.25 = 10.50

3 x 2.65 x 1.15 = 9.14

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Maint. of already planted trees —					
		40 x 1			40.00 Nos
Bar 05/53					
Abstract of Cost					
① Restoration of Raincoat —					
Qty. wire THB R (36)					
L = 45.56 m ² @ R 386.14/m ² —					R. 17593 =
② Making up of Beams —					
Qty. wire THB R (36)					
L = 202.50 m ² @ R 57.36/m ² —					R. 11615 =
③ Patch repair with 20 mm					
premix cement —					
Qty. wire THB R (36)					
L = 28.13 m ² @ R 257.10/m ² —					R. 7232 =
④ Maint. of already planted trees —					
Qty. wire THB R (37)					
40.00 Nos @ R 671.00/each —					R. 26840 =
					R. 63280 =
Acry. L.H. + L.H. —					R. 8226 =
Acry. S.F. —					R. 300 =
					R. 71806 =
Less Below 0.25% —					R. 180 =
					R. 71626 =
Bar 05/53					